

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001818/ETD3E2

Date: 15/03/2021

REFERENCE

Insured/Claimant:	CHONG WOEI SONG	Policy No:	1900001161	
Date of Loss:	06/02/2021	Nature of Claim:	OD	Claim No: 5953972271SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH9933C	Engine No:	G4FGJH715710
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF1416MK5027078
Reg. Date:	21/01/2019 (Man. Year: 2018)	Odometer:	33720 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$69,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	NFERA 5 mm	Rear Left Side:	NFERA 5 mm
Front Right Side:	NFERA 5 mm	Rear Right Side:	NFERA 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,894.00	1,086.00	1,808.00	62.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	900.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,794.00	1,986.00	1,808.00	47.65
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	3,494.00	1,686.00	1,808.00	51.75
+ GST 7.00/7.00% (S\$)	244.58	118.02	126.56	51.75
Nett Amount (S\$)	3,738.58	1,804.02	1,934.56	51.75

INSPECTION

Date of Assignment:	08/02/2021	
Date Inspected:	08/02/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER	Crushed	633.00 F	*633.00 FL
2	1		*GRILLE-FRONT BUMPER	Cut	262.00 F	*262.00 FL
3	1		*LAMP ASSY-DAY RUNNING LIGHT,LH	Not Necessary	203.00 F	*- FL
4	1		*MOULDING-FRONT BUMPER,LH	Cut	36.00 F	*36.00 FL
5	1		*LAMP ASSY-SIDE REPEATER,LH	Not Necessary	143.00 F	*- FL
6	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 F	*84.00 FL
7	1		*AIR DUCT-FR BUMPER,LH	Not Necessary	14.00 F	*- FL
8	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 F	*- FL
9	1		*GRILLE ASSY-RADIATOR	Cut	223.00 F	*223.00 FL
10	1		*ORNAMENT-KIA NO.115	Necessary	32.00 F	*32.00 FL
11	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 F	*- FL
12	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 F	*- FL
13	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
14	1		*FRT NUMBER PLATE WITH FRAME	Cut	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,894.00	1,340.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	254.00
Total Parts (\$)	2,894.00	1,086.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER	New	400.00	400.00
2	SPRAY PAINT FOR FRT BUMPER	New	350.00	350.00
3	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$\$)			900.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >