



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 05.02.2021
Emailed : 19.04.2021, 3.50pm
Date Survey : 08.02.2021

VEHICLE NO : SFZ 7767 S
MODEL : MIT OUTLANDER 2.0 SPORTS
WIP : 62784

Table with 2 columns: Description and Amount. Rows include Material (\$2,145.99), Labour (\$3,915.00), Sub-Total (\$6,060.99), Less Excess (\$300.00), Total (\$5,760.99), GST 7% (\$403.27), Grand Total (\$6,164.26), and Finalise By/Date (LOI / 19/04/2021).

[X] REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

[] SURVEYOR'S REPORT REQUIRED

[] REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends + 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[] TP claim

[] Claim GIA / LTA fee

[] Claim Loss of [] Use / [] Rental

[] Claim Medical Fee / Others

[] Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 17/02/2021	Cust No/Name	/Abdul Jalil Bin Mohamad
	Reg No/Reg Date	SFZ7767S / 12/02/2018
	Date In/Mileage	17/02/2021/ 116253
	Chassis/Package	GF7W0401119 /DC17S3C
	Engine No	4J11XK6012
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT SPORTS (992)
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/04/2021/ 15:34	BLD	260 / AiTing	62784

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE LH REAR DOOR, REPAIR LH SIDE SILL, LH FRONT DOOR, LH REAR FENDER, REAR BUMPER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 1125.00
E PNT88000 TRANSFER LH REAR DOOR TRIM, DOOR GLASS, MECHANISMS, AND ALL OTHER ATTACHMENTS TO NEW DOOR				✓ 120.00
E PNT88000 REMOVE AND INSTALL FLOOR CARPETS, SIDE CABIN TRIMS, AND ALL OTHER ATTACHMENTS TO FACILITATE REPAIR				✓ 120.00
E PNT98000 RESPRAY ON LH FRONT DOOR, LH REAR DOOR, LH SIDE SILL, LH REAR FENDER, REAR BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1750.00
E PNT88000 REMOVE AND INSTALL AERO KIT TO FACILITATE REPAIR				✓ 80.00
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREAS				✓ 40.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓ 30.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS				✓ 40.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE				✓ 120.00
A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT				✓ 120.00
M SUNDRY REAPPLY ZERTONA COATING ON AFFECTED AREAS				✓ 320.00
M SUNDRY SUNDRIES				✓ 20.00
S SPECIALISTJOB REPLACE LH REAR SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING				✓ 30.00
X EXC				-300.00

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 17/02/2021	Cust No/Name /Abdul Jalil Bin Mohamad Reg No/Reg Date SFZ7767S / 12/02/2018 Date In/Mileage 17/02/2021/ 116253 Chassis/Package GF7W0401119 /DC17S3C Engine No 4J11XK6012 Make/Model MIT/OUTLANDER 2.0 2WD CVT SPORTS (992) Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/04/2021/ 15:34	BLD	260 / AiTing	62784

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
INSURANCE EXCESS				
X PANEL ASSY,RR DOOR,LH	937 1.00	✓ 942.00	23.00	725.34
X TAPE,RR DOOR SASH	1.00	✓ 42.00	23.00	32.34
X TAPE,RR DOOR SASH	1.00	✓ 42.00	23.00	32.34
X GARNISH,FR DOOR,LH	1.00	✓ 190.00	23.00	146.30
X GARNISH,RR DOOR,LH	1.00	✓ 164.00	23.00	126.28
X WHEEL,SPARE TIRE DISC	1.00	✓ 1102.00	23.00	848.54
X MOULDING,RR WHEEL ARCH,LH	1.00	✓ 199.00	23.00	153.23
X MOULDING,RR BUMPER,LH	1.00	✓ 106.00	23.00	81.62
Z TEXT				
AIG OD CLAIM				
DOA : 05.02.21				
SURVEYOR STEVE LKK 08.02.21				
POLICY NO: 1800014507-01				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	2,145.99	Nett	5,760.99
Labour	3,465.00	7% GST on	5760.99
Standard Menu	0.00		
Specialist Job	30.00	Total Payable	6,164.26
Diagnostics Job	0.00		
Sundry/Others	120.00		
Total(w/o GST)	5,760.99		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

Work Order: R001362
 License: SFZ 7767 S
 Technician: 106 SOON 108 ALCIN
 Mileage: 116253
 Date: 25.2.21 17:40

Mitsubishi : Outlander/Airtrek : 2013- (GF/GG) : Front Wheel Drive

Front : Left

Actual	Before	Specified Range
0°02'	3°00'	-0°10' 0°50'
2°01**	3°00'	2°05' 3°05'
0°00'	0°00'	-0°02' 0°06'
14°29**	13°50'	11°15' 14°15'
14°31'	13°50'	11°05' 15°05'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°09'	3°00'	-0°10' 0°50'
3°02'	3°06**	2°05' 3°05'
0°02'	0°04'	-0°02' 0°06'
12°41'	12°15'	11°15' 14°15'
12°50'	12°23'	11°05' 15°05'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-3°07'	-0°05'	-0°30' 0°30'
-1°01**	-0°59**	-0°30' 0°30'
1°45'	1°39'	
0°04'	0°06'	-0°04' 0°12'

Rear : Left

Actual	Before	Specified Range
-0°44'	-0°45'	-1°15' 0°15'
0°07'	0°01**	0°02' 0°12'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°02'	-0°59'	-1°15' 0°15'
0°06'	0°09'	0°02' 0°12'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°13'	0°12'	-0°30' 0°30'
0°14'	0°10'	0°04' 0°24'
0°00'	-0°04'	

SFZ: 11/16/19.

All DTCS Diagnostic Check all systems

2021.02.25

Item	Setting	Information
M.U.T.-3 Version		SEW20091-00
V.C.I. Version		B178
Vehicle Information		DBA-GFTW 2017MY

All DTCs

2021.02.25

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MP/GDI/DIESEL	GAS_0E640000		No DTCs	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs	
AT/CVT/A-MT/T/C-SST	CVT_14080300		No DTCs	
AUTO CRUISE	GAS_0E640000		Non-target System	
4VWS/Electric Power Steering	EPS_45880040		No DTCs	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs	
SRS-AIR BAG	ORC_81047302		No DTCs	
Air Conditioner	AC_80080011		No DTCs	
ETACS	ETACS_83040801		No DTCs	
Meter	MTR_84084001		No DTCs	
Steering Angle Sensor	GS_SYS_47000100		Non-target System	
AND	AND_8C080002		Non-equipped System or Communication Error	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000	U0184	AUDIO CAN timeout	Active

All DTCS

2021.02.25

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/keyless	KOS_8A880020		No DTCS	
OSS	OSS_9588000B		No DTCS	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACC/FCM_4B080000		Non-equipped System or Communication Error	
Multi-Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	