

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001833/EVF3E2

Date: 04/03/2021

REFERENCE

Insured/Claimant:	GOH PUAY KEE	Policy No:	1800090538		
Date of Loss:	05/02/2021	Nature of Claim:	OD	Claim No:	4624356157SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD570X	Engine No:	4B40DR0518
Make & Model:	MITSUBISHI ECLIPSE CROSS, 1.5 (A)	Chassis No:	JMAXTGK1WJZ002793
Reg. Date:	31/07/2018 (Man. Year: 2018)	Odometer:	59380 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$84,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R18	Rear Tyre Size:	255/55 R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,807.00	5,346.86	10,460.14	66.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,210.00	2,925.00	2,285.00	43.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,017.00	8,271.86	12,745.14	60.64
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	20,617.00	7,871.86	12,745.14	61.82
+ GST 7.00/7.00% (\$\$)	1,443.19	551.03	892.16	61.82
Nett Amount (\$\$)	22,060.19	8,422.89	13,637.30	61.82

INSPECTION

Date of Assignment:	08/02/2021	
Date Inspected:	08/02/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FACE, FR BUMPER	Dented	714.00 F	*714.00 FL
3	1		*GARNISH, FR BUMPER SIDE	Cut	73.00 F	*73.00 FL
4	1		*GARNISH, FR BUMPER SIDE	Broken	214.00 F	*214.00 FL
5	1		*EXTENSION, FR BUMPER	Not Necessary	317.00 F	*- FL
6	1		*COVER, FR BUMPER	Not Necessary	380.00 F	*- FL
7	1		*BRACKET, FR BUMPER SIDE, LH	Broken	18.00 F	*18.00 FL
8	1		*REINFORCEMENT, FR BUMPER	Not Necessary	552.00 F	*- FL
9	1		*REINFORCEMENT, FR BUMPER	Not Necessary	235.00 F	*- FL
10	1		*REINF, FR BUMPER SIDE, LH	Not Necessary	35.00 F	*- FL
11	1		*BAR, FR BUMPER GUARD	Not Necessary	100.00 F	*- FL
12	1		*GRILLE ASSY, RADIATOR	Not Necessary	484.00 F	*- FL
13	1		*COVER, FR BUMPER GRILLE	Not Necessary	302.00 F	*- FL
14	1		*INSULATOR, FR FENDER, LH	Torn	52.00 F	*52.00 FL
15	1		*FENDER, FR LH	Dented	599.00 F	*599.00 FL
16	1		*SHIELD, FR WHEELHOUSE, LH	Crushed	135.00 F	*135.00 FL
17	1		*PAD, FR FENDER	Not Necessary	57.00 F	*- FL
18	1		*COVER, ENG ROOM UNDER, FR	Not Necessary	158.00 F	*- FL
19	1		*MOULDING, FR WHEEL ARCH, LH	Cut	151.00 F	*151.00 FL
20	1		*GARNISH, SIDE SILL, LH	Not Necessary	91.00 F	*- FL
21	1		*GARNISH, FR PILLAR, LH	Not Necessary	123.00 F	*- FL
22	1		*MIRROR ASSY, DOOR, LH	Not Necessary	824.00 F	*- FL
23	1		*COVER, DOOR MIRROR, OTR LH	Repair	100.00 F	*- FL
24	1		*HEADLAMP ASSY, LH	Broken	1,976.00 F	*1,976.00 FL
25	1		*BRACKET, HEADLAMP	Not Necessary	16.00 F	*- FL
26	1		*BRACKET, HEADLAMP	Not Necessary	12.00 F	*- FL
27	1		*WHEEL, DISC	Cut	1,102.00 F	*1,102.00 FL
28	1		*SHAFT AS, FR AXLE DRIVE, LH	Not Necessary	1,106.00 F	*- FL
29	1		*ARM ASSY, FR SUSP, LWR LH	Bent	323.00 F	*323.00 FL
30	1		*CROSSMEMBER, FR AXLE, NO.1	Not Necessary	1,114.00 F	*- FL
31	1		*HUB ASSY, FR WHEEL	Not Necessary	383.00 F	*- FL
32	1		*KNUCKLE, LH	Not Necessary	346.00 F	*- FL
33	1		*STRUT, FR SUSP, LH	Bent	413.00 F	*413.00 FL
34	1		*LINK, FR SUSP STABILIZER	Bent	137.00 F	*137.00 FL
35	1		*BAR, FR SUSP STABILIZER	Not Necessary	291.00 F	*- FL
36	1		*BEARING, FR SUSP STRUT	Necessary	32.00 F	*32.00 FL
37	1		*INSULATOR, FR SUSP STRUT	Bent	136.00 F	*136.00 FL
38	1		*PAD, FR SUSP SPRING, LWR	Not Necessary	15.00 F	*- FL
39	1		*GEAR & LINK ASSY, STEERING	Not Necessary	1,399.00 F	*- FL
40	1		*END ASSY, TIE ROD	Not Necessary	76.00 F	*- FL
41	1		*SENSOR, FR ABS, LH	Not Necessary	240.00 F	*- FL
42	1		*ACTUATOR, HEADLAMP WASHER, L	Not Necessary	113.00 F	*- FL
43	1		*LAMP A,T/SIG & FOG, FR LH (Supplementary)	Broken	506.00 F	*506.00 FL
44	1		*HARNESS,FOG LAMP (Supplementary)	Broken	298.00 F	*298.00 FL
45	1		*VALVE,TIRE (Supplementary)	Necessary	39.00 F	*39.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,807.00	6,938.00
- List Item Discount on L Items 0.00/23.00% (\$)	0.00	1,591.14
Total Parts (\$)	15,807.00	5,346.86

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT FENDER LH, REPAIR FRT WHEELHOUSING LH, FRT DOOR LH, BONNET	New	2,250.00	1,125.00
2	SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, BONNET, FRT DOOR LH, FRT WHEEL HOUSING LH	New	1,750.00	1,050.00
3	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	RENEW FRT UNDER CARRIAGE	New	450.00	450.00
6	TRANSFER FRT LEFT RIM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	SUPPLY FRT LEFT TYRE	New	460.00	0.00
Gross Labour Cost (\$)			5,210.00	2,925.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >