

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001838/T1GS3Q2
Date: 16/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800077870-01
Claimant Vehicle No :	SLF3903B	Insured Vehicle No :	SJS2255A
Date of Loss:	06/02/2021	Nature of Claim:	TP
		Claim No:	0067580396SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF3903B		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	2ZR1823973
Reg. Date:	25/08/2016 (Man. Year: 2016)	Chassis No:	JTDGG20W30J004936
Colour:	Purple	Odometer:	342342 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,985.87	7,147.49	8,838.38	55.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,210.00	2,620.00	1,590.00	37.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,195.87	9,767.49	10,428.38	51.64
Approved Total (Overridden) (S\$)		7,800.00		

(S\$)	20,195.87	7,800.00	12,395.87	61.38
+ GST 7.00/7.00% (S\$)	1,413.71	546.00	867.71	61.38
Nett Amount (S\$)	21,609.58	8,346.00	13,263.58	61.38
+ Car Rental (9.0 x S\$120.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,433.45		

INSPECTION

Date of Assignment: 08/02/2021

Date Inspected: 08/02/2021

Estimated Period of Repair: 8.0 days

Inspected At:

Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
 Singapore 408934

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	765.50 FL	*491.90 FL
2	1		*REAR BUMPER RETAINER	N/S Deformed / O/S Not Necessary	151.20 FL	*75.60 FL
3	1		*REAR BUMPER BRACKET	N/S Cracked / O/S Not Necessary	120.30 FL	*60.15 FL
4	1		*REAR BUMPER REFLECTOR	N/S Cracked / O/S Not Necessary	173.60 FL	*86.80 FL
5	1		*END PANEL	Bent	803.87 FL	*645.10 FL
6	1		*END PANEL TOP GARNISH	Deformed	382.61 FL	*218.97 FL
7	1		*KEYLESS SENSOR	Cracked	281.60 FL	*189.50 FL
8	1		*KEYLESS SENSOR HOLDER	Cracked	102.20 FL	*102.20 FL
9	1		*TAILGATE	Bent	1,370.62 FL	*1,175.00 FL
10	1		*TAILGATE WEATHERSTRIP	Cut	229.10 FL	*229.10 FL
11	1		*TAILGATE LOCK	Bent	509.20 FL	*361.60 FL
12	1		*TAILGATE EMBLEM -VALVE MATIC (2 PCS)	Necessary	54.59 FL	*54.59 FL
13	1		*TAILGATE EMBLEM -LOGO	Necessary	65.29 FL	*65.29 FL
14	1		*TAILGATE GLASS MOULDING	Necessary	180.00 FL	*180.00 FL
15	1		*TAILGATE OUTER CHROME GARNISH	Not Necessary	386.50 FL	*- FL
16	1		*TAILGATE LAMP	N/S Necessary / O/S Not Necessary	854.56 FL	*387.50 FL
17	1		*TAILGATE INNER TRIM BOARD	Cut	331.90 FL	*299.70 FL
18	1		*FRONT BUMPER	Deformed	565.80 FL	*565.80 FL
19	2		*FRONT BUMPER COVER	Not Necessary	287.50 FL	*- FL
20	2		*FRONT BUMPER RETAINER	Not Necessary	138.00 FL	*- FL
21	1		*FRONT BUMPER REINFORCEMENT	Bent	327.35 FL	*327.35 FL
22	1		*FRONT BUMPER SPONGE	Cracked	115.00 FL	*115.00 FL
23	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	126.50 FL	*- FL
24	1		*FRONT GRILLE	Cracked	454.25 FL	*286.20 FL
25	1		*FRONT GRILLE EMBLEM	Not Necessary	55.00 FL	*- FL
26	1		*FRONT SUPPORT PANEL	Repair	1,477.50 FL	*- FL
27	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	292.10 FL	*- FL
28	1		*BONNET	Bent	931.50 FL	*787.00 FL
29	1		*BONNET LOCK	Not Necessary	109.25 FL	*- FL
30	1		*BONNET INSULATOR	Not Necessary	454.24 FL	*- FL
31	2		*BONNET HINGE	Repair	126.50 FL	*- FL
32	1		*BONNET EMBLEM -LOGO	Necessary	91.30 FL	*91.30 FL
33	1		*AIRCON CONDENSER	Not Necessary	1,725.00 FL	*- FL
34	1		*RADIATOR	Not Necessary	2,305.75 FL	*- FL
35	2		*FRONT HEADLAMP	Cracked	2,185.00 FL	*1,900.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
37	1		*SET FRONT GRILLE CLIP	Necessary	30.00 FS	*20.00 FS
38	1		*SET BONNET INSULATOR CLIP	Not Necessary	20.00 FS	*- FS
39	1		*BOT COOLANT	Not Necessary	60.00 FS	*- FS
40	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
41	1		*SET REAR BUMPER PLATE	Bent	80.00 FS	*45.00 FS
42	1		*SET WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
43	1		*SET REVERSE SENSOR	Not Working	400.00 FS	*200.00 FS
44	1		*TAILLAMP LH	Cracked	527.38 FL	*321.00 FL
45	1		*SPARE TYRE COMPARTMENT	Repair	1,203.60 FL	*- FL
					Sub Total (S\$)	21,051.16
					- List Item Discount on L Items 25.00/25.00% (S\$)	5,065.29
					Total Parts (S\$)	15,985.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE RENEW CONDENSER AND TOP UP GAS	New	200.00	0.00
3	REMOVE RENEW RADIATOR AND TOP UP COOLANT	New	200.00	0.00
4	REMOVE ,REFIT REAR WINDSCREEN	New	200.00	120.00
5	REMOVE REFIT AND REPLACE REVERSE SENSOR	New	200.00	30.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	1,200.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,200.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
Gross Labour Cost (S\$)			4,210.00	2,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >