

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC4/AIG21001846/GGS3Q2  
**Date:** 18/05/2021

**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2070126882   |
| <b>Claimant Vehicle No :</b> | SHD1153U                             | <b>Insured Vehicle No :</b> | SMU8171Y     |
| Date of Loss:                | 06/02/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 5906837265SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                        |             |                   |
|-----------------------------|----------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SHD1153U</b>                        |             |                   |
| Make & Model:               | HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M) | Engine No:  | D4FBGZ114408      |
| Reg. Date:                  | 15/02/2017 (Man. Year: 2016)           | Chassis No: | TMAD281UVHJ124399 |
| Colour:                     | Silver                                 | Odometer:   | 311164 km         |
| Engine Capacity:            | 1582 cc                                |             |                   |
| Market Value/New Car Price: | N/A                                    |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>      |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 195/65 R15  | Rear Tyre Size:  | 195/65 R15  |
| Front Left Side:  | Maxxis 6 mm | Rear Left Side:  | Maxxis 6 mm |
| Front Right Side: | Maxxis 6 mm | Rear Right Side: | Maxxis 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 3,407.87          | 1,150.74          | 2,257.13          | 66.23         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 1,940.00          | 540.00            | 1,400.00          | 72.16         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>5,347.87</b>   | <b>1,690.74</b>   | <b>3,657.13</b>   | <b>68.38</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>1,350.00</b>   |                   |               |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| (S\$)                                           | 5,347.87        | 1,350.00        | 3,997.87        | 74.76        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 374.35          | 94.50           | 279.85          | 74.76        |
| <b>Nett Amount (S\$)</b>                        | <b>5,722.22</b> | <b>1,444.50</b> | <b>4,277.72</b> | <b>74.76</b> |
| <b>+ Loss of Use (2.0 x S\$40.00/day) (S\$)</b> |                 | 80.00           |                 |              |
| <b>+ Car Rental (2.0 x S\$57.41/day) (S\$)</b>  |                 | 114.82          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 2.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>1,641.32</b> |                 |              |

INSPECTION

Date of Assignment: 08/02/2021

Date Inspected: 22/02/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)  
 23 Changi South Ave 2, #01-02  
 Singapore 486443

**Adjuster:** XING GUO QIANG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's | Amount     |
|-----|-----|----------|-------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *TAILGATE LOWER GARNISH             | Cracked       | 362.61 FL  | *362.61 FL |
| 2   | 1   |          | *TAILGATE LOCK                      | Not Necessary | 216.48 FL  | *- FL      |
| 3   | 1   |          | *TAILGATE STRIKER                   | Not Necessary | 36.50 FL   | *- FL      |
| 4   | 1   |          | *TAILGATE INNER TRIM                | Not Necessary | 431.12 FL  | *- FL      |
| 5   | 1   |          | *TAILGATE WEATHERSTRIP              | Not Necessary | 276.98 FL  | *- FL      |
| 6   | 1   |          | *EMBLEM I30                         | Necessary     | 27.80 FL   | *27.80 FL  |
| 7   | 1   |          | *EMBLEM CRDI                        | Necessary     | 29.40 FL   | *29.40 FL  |
| 8   | 1   |          | *EMBLEM HYUNDAI                     | Not Necessary | 29.40 FL   | *- FL      |
| 9   | 1   |          | *REAR BUMPER                        | Deformed      | 811.11 FL  | *811.11 FL |
| 10  | 1   |          | *REAR BUMPER SPONGE                 | Not Necessary | 79.20 FL   | *- FL      |
| 11  | 1   |          | *REAR BUMPER REINFORCEMENT          | Not Necessary | 815.64 FL  | *- FL      |
| 12  | 1   |          | *REAR BUMPER REINFORCEMENT CENTRE   | Not Necessary | 79.20 FL   | *- FL      |
| 13  | 2   |          | *REAR BUMPER N/S & O/S SIDE BRACKET | Not Necessary | 104.40 FL  | *- FL      |
| 14  | 2   |          | *REAR BUMPER N/S & O/S REFLECTOR    | Not Necessary | 215.00 FL  | *- FL      |
| 15  | 1   |          | *SET REAR BUMPER CLIPS              | Necessary     | 48.00 FS   | *48.00 FS  |
| 16  | 1   |          | *SET REVERSE SENSOR                 | Not Necessary | 280.00 FS  | *- FS      |
| 17  | 1   |          | *SET TAILGATE STICKERS              | Necessary     | 100.00 FS  | *30.00 FS  |
| 18  | 1   |          | *SET TAILGATE LOWER GARNISH CLIPS   | Necessary     | 38.00 FS   | *38.00 FS  |
| 19  | 1   |          | *REAR BUMPER TOP PROTECTOR          | Deformed      | 80.00 FS   | *50.00 FS  |
| 20  | 1   |          | *SUNDRY                             | Not Necessary | 50.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>4,110.84</b> | <b>1,396.92</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 702.97          | 246.18          |
| <b>Total Parts (\$\$)</b>                                  | <b>3,407.87</b> | <b>1,150.74</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                                                                          | Lab.Type | Repairer's      | Amount        |
|--------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|---------------|
| <b><u>Labour Items</u></b>     |                                                                                                                                                                                      |          |                 |               |
| 1                              | TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM                                                                                                                              | New      | 80.00           | 40.00         |
| 2                              | TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS                                                                 | New      | 180.00          | 0.00          |
| 3                              | TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO HEAT/CUT AND WELD ON THE END PANEL .INCLUDING TO KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE OF THE TAILGATE ETC | New      | 800.00          | 200.00        |
| 4                              | TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE ,TAILGATE LOWER GARNISH ,END PANEL ,TAILGATE                                                                                | New      | 800.00          | 300.00        |
| 5                              | TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS                                                                                                                            | New      | 80.00           | 0.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                                                                      |          | <b>1,940.00</b> | <b>540.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >