

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III21001848/ATD3Q2
Date: 16/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLQ2173P	Insured Vehicle No :	SMH9414J
Date of Loss:	05/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000573

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ2173P	Engine No:	R16A12003277
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	JHMFD46207S201348
Reg. Date:	23/10/2007 (Man. Year: 2007)	Odometer:	239955 km
Colour:	White		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,501.36	6,006.88	3,494.48	36.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,660.00	1,290.00	43.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,451.36	7,666.88	4,784.48	38.43
Approved Total (Overridden) (S\$)		6,100.00		

Nett Amount (S\$)

12,451.36

6,100.00

6,351.36

51.01

INSPECTION

Date of Assignment: 08/02/2021

Date Inspected: 08/02/2021

Estimated Period of Repair: 6.0 days

Inspected At:

MCS GARAGE (HQ)
10 KAKI BUKIT ROAD 2, #03-25 FIRST EAST CENTRE
Singapore 417868

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Jun 2021)
Parts: 143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLQ2173P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	881.90 FL	*638.00 FL
2	1		*FRONT BUMPER SIDE RETAINER -L/R	O/S Damaged	77.20 FL	*38.60 FL
3	1		*FRONT BUMPER SIDE GRILLE -RH	Not Necessary	86.90 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	381.70 FL	*- FL
5	1		*FRONT FENDER -RH	Buckled	584.60 FL	*584.60 FL
6	1		*FRONT FENDER INNER SHIELD	Torn	154.50 FL	*154.50 FL
7	1		*FRONT HEADLAMP -RH	Cut	1,035.60 FL	*912.00 FL
8	1		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	86.90 FL	*- FL
9	1		*FRONT SHOCK ABSORBER -RH	Bent	441.20 FL	*334.00 FL
10	1		*FRONT LOWER ARM	Bent	420.60 FL	*365.00 FL
11	1		*FRONT KNUCKLE ARM	Damaged	416.50 FL	*416.50 FL
12	1		*FRONT WHEEL HUB	Damaged	281.60 FL	*281.60 FL
13	1		*FRONT WHEEL BEARING	Necessary	181.20 FL	*181.20 FL
14	1		*FRONT ANTI ROLL BAR	Not Necessary	421.60 FL	*- FL
15	1		*FRONT ANTI ROLL BAR LINK	Bent	110.20 FL	*110.20 FL
16	1		*FRONT DRIVE SHAFT	Not Necessary	1,260.50 FL	*- FL
17	1		*FRONT STEERING RACK ASSY	Broken	1,860.90 FL	*1,860.90 FL
18	1		*FRONT STEERING RACK CROSSMEMBER	Bent	1,150.90 FL	*1,150.90 FL
19	1		*FRONT BALL JOINT	Damaged	180.60 FL	*180.60 FL
20	1		*FRONT BRAKE SENSOR -A.B.S	Not Necessary	221.90 FL	*- FL
21	1		*FRONT WIPER ARM	Not Necessary	152.20 FL	*- FL
22	1		*FRONT SPORT WHEEL	Not Necessary	650.00 FS	*- FS
23	1		*FRONT TYRE	Cut	450.00 FS	*180.00 FS
24	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
25	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	45.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)
11,579.20
7,448.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE ,REFIX FRONT UNDERCARRIAGE	New	450.00	350.00
3	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
4	TOWING CHARGES -2 TRIPS	New	120.00	60.00
5	TO RESPRAY UNDERCOATING	New	80.00	40.00
6	TO RESPRAY PAINTING AND ETC	New	1,080.00	500.00
7	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	1,050.00	600.00
			Gross Labour Cost (S\$)	2,950.00
				1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >