

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001853/ETD3E2

Date: 19/03/2021

REFERENCE

Insured/Claimant: LOO WEI HAO Policy No: 2070124947
Date of Loss: 06/02/2021 Nature of Claim: OD Claim No: 5745909540SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU9123E**
Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11CM9052
Reg. Date: 03/09/2020 (Man. Year: 2020) Chassis No: GF7W0700599
Colour: Red Odometer: 16691 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$110,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Toyo 4 mm Rear Left Side: Toyo 4 mm
Front Right Side: Toyo 4 mm Rear Right Side: Toyo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,992.66	3,117.71	1,874.95	37.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,620.00	2,640.00	2,980.00	53.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,612.66	5,757.71	4,854.95	45.75
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	10,312.66	5,457.71	4,854.95	47.08
+ GST 7.00/7.00% (S\$)	721.89	382.04	339.85	47.08
Nett Amount (S\$)	11,034.55	5,839.75	5,194.80	47.08

INSPECTION

Date of Assignment: 08/02/2021
Date Inspected: 08/02/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*FACE, RR BUMPER	Cut	811.00 FL	*811.00 FL
3	1		*EXTENSION, RR BUMPER	Cut	292.00 FL	*292.00 FL
4	1		*BRKT, R/BMPR FACE, SIDE, LH	Not Necessary	12.00 FL	*- FL
5	1		*BRKT, R/BMPR FACE SIDE, RH	Not Necessary	12.00 FL	*- FL
6	1		*REINFORCEMENT, RR BUMPER, RH	Not Necessary	79.00 FL	*- FL
7	1		*REINFORCEMENT, RR BUMPER, LH	Not Necessary	79.00 FL	*- FL
8	1		*PANEL ASSY, TAILGATE	Dented	989.00 FL	*989.00 FL
9	1		*GARNISH, TAILGATE	Broken	496.00 FL	*496.00 FL
10	1		*DAM, TAILGATE, UPR	Necessary	13.00 FL	*13.00 FL
11	2		*DAM, TAILGATE SIDE	Necessary	54.00 FL	*54.00 FL
12	2		*STOPPER, WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
13	1		*DAM, TAILGATE, LWR	Necessary	41.00 FL	*41.00 FL
14	1		*FASTENER, WINDSHIELD	Necessary	6.00 FL	*6.00 FL
15	1		*LATCH, TAILGATE	Not Necessary	383.00 FL	*- FL
16	1		*STRIKER, TAILGATE LATCH	Not Necessary	20.00 FL	*- FL
17	1		*W//STRIP, TAILGATE OPENING	Not Necessary	213.00 FL	*- FL
18	1		*PANEL, RR END	Not Necessary	324.00 FL	*- FL
19	1		*TRIM, RR END	Not Necessary	113.00 FL	*- FL
20	1		*LAMP ASSY, COMB, RR LH	Not Necessary	600.00 FL	*- FL
21	1		*LAMP ASSY, COMB, RR RH	Not Necessary	600.00 FL	*- FL
22	1		*LAMP ASSY, TAIL, LH	Broken	506.00 FL	*506.00 FL
23	1		*LAMP ASSY, TAIL, RH	Broken	506.00 FL	*506.00 FL
24	1		*HANDLE, TAILGATE LOCK RLSE (Supplementary)	Broken	202.00 FL	*202.00 FL
25	1		*FASTENER, WINDSHIELD (Supplementary)	Necessary	6.00 FL	*6.00 FL
26	1		*MARK, OUTLANDER	Necessary	95.00 FL	*95.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,478.00	4,043.00
- List Item Discount on L Items 23.00/23.00% (\$)	1,485.34	925.29
Total Parts (\$)	4,992.66	3,117.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
Labour Items					
1	RENEW RR BUMPER, TAILGATE & RR END PNL. REPAIR / ALIGN LHR FENDER, RHR FENDER & RR FLR PNL	New	2,250.00	900.00	
2	RESPRAY RR BUMPER, RR END PNL, TAILGATE, RR FLR PNL, LHR FENDER & RHR FENDER	New	2,100.00	960.00	
3	REMOVE & REFIT TAILGATE COMPONENTS	New	120.00	120.00	
4	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET TO FACILITATE REPAIR	New	120.00	0.00	
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00	
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00	
7	REMOVE & REFIT RR WINDSCREEN GLASS	New	240.00	240.00	
8	SUPPLY RR WINDSCREEN SEALANT	New	80.00	80.00	
9	SUPPLY RR NUMBER PLATE WITH CASING	New	50.00	0.00	
10	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00	
11	SUPPLY REVERSE SENSOR	New	220.00	0.00	
12	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	0.00	
13	SUPPLY BODY PNL SEALANT	New	60.00	40.00	
14	SUPPLY C&C BADGE	New	40.00	40.00	
15	SUPPLY OUTLANDER EMBLEM (NPA)	New	0.00	0.00	
16	SUPPLY MIVEC EMBLEM (Supplementary)	New	50.00	50.00	
			Gross Labour Cost (\$\$)	5,620.00	2,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >