



**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**ESTIMATE**

GST Reg No : MR-8500111-X

Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/LOO WEI HAO
	Reg No/Reg Date	SMU9123E / 03/09/202
	Date In/Mileage	/ 0
	Chassis No	GF7W0700599
	Engine No	4J11CM9052
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (
Colour/Trim	P62 RED DIAMOND / BK BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	08/02/2021/ 13:35	QUE	261 / Edwin Caina	62752

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER, TAILGATE & RR END PNL REPAIR / ALIGN LHR FENDER, RHRNFENDER & RR FLR PNL	450 X 2			999 2250.00
E PNT98000 RESPRAY RR BUMPER, RR END PNL, TAILGATE, RR FLR PNL, LHR FENDER & RHR FENDER	350 X 2	960		790 2100.00
E PNT88000 REMOVE & REFIT TAILGATE COMPONENTS				✓ 120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD, TRIM & CARPET TO FACILITATE REPAIR				? X 120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
E PNT88000 REMOVE & REFIT RR WINDSCREEN GLASS				240.00
M SUNDRY SUPPLY RR WINDSCREEN SEALANT				80.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING				50.00 X
E PNT88000 REMOVE & REFIT REVERSE SENSOR				60.00
M SUNDRY SUPPLY REVERSE SENSOR				220.00 X
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				? X 80.00
M SUNDRY SUPPLY BODY PNL SEALANT				40 60.00
M SUNDRY SUPPLY C&C BADGE				40.00
M SUNDRY Sundries				20.00

**Estimate**

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name / LOO WEI HAO Reg No/Reg Date SMU9123E / 03/09/202 Date In/Mileage / 0 Chassis No GF7W0700599 Engine No 4J11CM9052 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( ) Colour/Trim P62 RED DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
KAX00008	Credit	08/02/2021/ 13:35	QUE	261 / Edwin Caina	62752				
<b>Description of Goods / Services</b>									
M SUNDRY									
M SUPPLY OUTLANDER EMBLEM (TBA)						1.00	811	23.00	621.39
M FACE, RR BUMPER						1.00	292.00	23.00	224.84
M EXTENSION, RR BUMPER						1.00	12.00	23.00	9.24
M BRKT, R/BMPR FACE SIDE, LH NN						1.00	12.00	23.00	9.24
M BRKT, R/BMPR FACE SIDE, RH NN						1.00	79.00	23.00	60.83
M REINFORCEMENT, RR BUMPER, RH NN						1.00	79.00	23.00	60.83
M REINFORCEMENT, RR BUMPER, LH NN						1.00	989	23.00	757.68
M PANEL ASSY, TAILGATE						1.00	496	23.00	365.75
M GARNISH, TAILGATE						1.00	13.00	23.00	10.01
M DAM, TAILGATE, UPR						2.00	27.00	23.00	41.58
M DAM, TAILGATE SIDE						2.00	3.00	23.00	4.62
M STOPPER, WINDSHIELD GLASS						1.00	41.00	23.00	31.57
M DAM, TAILGATE, LWR						1.00	6.00	23.00	4.62
M FASTENER, WINDSHIELD						1.00	383.00	23.00	294.91
M LATCH, TAILGATE						1.00	20.00	23.00	15.40
M STRIKER, TAILGATE LATCH						1.00	213.00	23.00	164.01
M W/STRIP, TAILGATE OPENING						1.00	324.00	23.00	249.48
M PANEL, RR END						1.00	113.00	23.00	87.01
M TRIM, RR END						1.00	600.00	23.00	462.00
M LAMP ASSY, COMB, RR LH						1.00	600.00	23.00	462.00
M LAMP ASSY, COMB, RR RH						1.00	506	23.00	389.62
M LAMP ASSY, TAIL, LH						1.00	506	23.00	389.62
M LAMP ASSY, TAIL, RH						1.00	506	23.00	389.62

**Estimate**

Steve (CLKK)  
 8/2/21, 2:00pm  
 OO- NH A/L  
 Excess - ?  
 P/P

LYK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting

**Confirm & accepted by** to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Authorized signatory and company stamp

By Bel spm  
 5 days

	<b>Nett</b>	<b>10,306.25</b>
<b>7% GST on</b>	<b>10306.25</b>	<b>721.44</b>
<b>Total Payable</b>		<b>11,027.69</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.