

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001856/EQF3Q2

Date: 19/03/2021

REFERENCE

Insured/Claimant:	HENG HANN JEN	Policy No:	2100504589	
Date of Loss:	07/02/2021	Nature of Claim:	OD	Claim No: 2962046477SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM1366C			
Make & Model:	KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A)	Engine No:	G4LEHS166685	
Reg. Date:	22/03/2017 (Man. Year: 2017)	Chassis No:	KNACC81CVH5052717	
Colour:	White	Odometer:	45113 km	
Engine Capacity:	1580 cc			
Market Value/New Car Price:	S\$72,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,016.80	6,737.60	2,279.20	25.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,960.00	2,990.00	1,970.00	39.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,976.80	9,727.60	4,249.20	30.40
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	13,676.80	9,427.60	4,249.20	31.07
+ GST 7.00/7.00% (S\$)	957.38	659.93	297.45	31.07
Nett Amount (S\$)	14,634.18	10,087.53	4,546.65	31.07

INSPECTION

Date of Assignment: 08/02/2021

Date Inspected: 08/02/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-HOOD	Dented	1,222.00 FL	*1,222.00 FL
2	1		*HINGE ASSY-HOOD,LH	Not Necessary	40.00 FL	*- FL
3	1		*HINGE ASSY-HOOD,RH	Not Necessary	40.00 FL	*- FL
4	14		*CLIP-HOOD INSULATING PAD MTG	Necessary	14.00 FL	*14.00 FL
5	1		*LATCH ASSY-HOOD	Not Necessary	123.00 FL	*- FL
6	1		*COVER-FR BUMPER UPR	Dented	632.00 FL	*632.00 FL
7	1		*CAP-FRONT HOOK	Crushed	7.00 FL	*7.00 FL
8	1		*COVER ASSY-FR BUMPER LWR	Broken	346.00 FL	*346.00 FL
9	1		*PIECE-FRT BUMPER GUARD LWR,LH	Not Necessary	16.00 FL	*- FL
10	1		*PIECE-FRT BUMPER GUARD LWR,RH	Not Necessary	16.00 FL	*- FL
11	1		*LOGO ASSY-KIA SUB	Necessary	51.00 FL	*51.00 FL
12	1		*STRIP ASSY-FR BUMPER UPR	Not Necessary	28.00 FL	*- FL
13	1		*GRILLE ASSY-RADIATOR	Cut	441.00 FL	*441.00 FL
14	1		*COVER ASSY-RADIATOR GRILLE UPR	Broken	40.00 FL	*40.00 FL
15	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	68.00 FL	*68.00 FL
16	1		*GRILLE-FRONT BUMPER	Broken	232.00 FL	*232.00 FL
17	1		*WIRING HARNESS-FR BUMPER	Broken	134.00 FL	*134.00 FL
18	1		*STIFFNER-FR BPR LWR	Not Necessary	116.00 FL	*- FL
19	1		*FLAP ASSY-ACTIVE AIR,LWR	Broken	328.00 FL	*328.00 FL
20	1		*DUCT ASSY-ACTIVE AIR	Broken	78.00 FL	*78.00 FL
21	1		*BRACKET-FR BUMPER SIDE,LH	Not Necessary	12.00 FL	*- FL
22	1		*BRACKET-FR BUMPER SIDE,RH	Not Necessary	12.00 FL	*- FL
23	1		*BEAM COMPLETE-FR BUMPER	Dented	551.00 FL	*551.00 FL
24	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
25	1		*CONDENSER ASSY-COOLER	Bent	639.00 FL	*639.00 FL
26	1		*RADIATOR ASSY-INVERTER	Bent	768.00 FL	*768.00 FL
27	1		*RADIATOR ASSY	Bent	492.00 FL	*492.00 FL
28	1		*BLOWER ASSY	Broken	546.00 FL	*546.00 FL
29	1		*GUARD AIR-LH	Crushed	29.00 FL	*29.00 FL
30	1		*GUARD AIR-RH	Broken	29.00 FL	*29.00 FL
31	1		*GUARD AIR RADIATOR,UPR	Crushed	15.00 FL	*15.00 FL
32	1		*LAMP ASSY-HEAD,LH	Not Necessary	904.00 FL	*- FL
33	1		*LAMP ASSY-HEAD,RH	Not Necessary	904.00 FL	*- FL
34	1		*LAMP ASSY-FRONT FOG & DRL,LH	Not Necessary	638.00 FL	*- FL
35	1		*LAMP ASSY-FRONT FOG & DRL,RH	Broken	638.00 FL	*638.00 FL
36	1		*COOLANT (4L)	Necessary	26.00 FL	*26.00 FL
37	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
38	1		*WIRING ASSY-FEM (Supplementary)	Broken	247.00 FL	*247.00 FL
39	1		*SPEAKER ASSY-VESS (Supplementary)	Broken	149.00 FL	*149.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,266.00	8,417.00
- List Item Discount on L Items 20.00/20.00% (\$)	2,249.20	1,679.40
Total Parts (\$)	9,016.80	6,737.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW FRT BUMPER,BONNET & FRT SUPPORT PNL,REPAIR/ALIGN LHF FENDER & RHF FENDER	New	2,400.00	800.00
2	RESPRAY FRT BUMPER,BONNET,LHF FENDER & RHF FENDER	New	1,400.00	1,050.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	80.00	80.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	50.00
8	SUPPLY BODY PNL SEALANT	New	60.00	40.00
9	DISCONNECT MAIN BATTERY CABLE TO FACILITATE REPAIR	New	120.00	120.00
10	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	400.00	400.00
11	REPAIR LH & RH FRONT MEMBER INCLUDING PAINT (Supplementary)	New	200.00	200.00
Gross Labour Cost (\$)			4,960.00	2,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >