



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /HENG HANN JEN Reg No/Reg Date SLM1366C / 22/03/201 Date In/Mileage / 45113 Chassis No KNACC81CVH5052717 Engine No G4LEHS166685 Make/Model KIA/NIRO 1.6 A Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	08/02/2021/ 11:59	BLE	261 / Edwin Caina	28726		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000				400 X 2			2400.00
RENEW FRT BUMPER , BONNET & FRT SUPPORT PNL							
REPAIR / ALIGN LHF FENDER & RHF FENDER							
E PNT98000				350 X 3			1400.00
RESPRAY FRT BUMPER , BONNET , LHF FENDER & RHF FENDER							
E PNT88000							100.00
REMOVE & REFIT AC COND & RADIATOR							
M SUNDRY							80.00
TOP UP AIRCON GAS							
A 54900099							30.00
CHECK WIRING ELECTRICAL SYSTEM							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							50.00
SUPPLY FRT NUMBER PLATE WITH CASING							
M SUNDRY							40 60.00
SUPPLY BODY PNL SEALANT							
M SUNDRY							20.00
Sundries							
A 54900099							120.00
DISCONNECT MAIN BATTERY CABLE TO FACILITATE REPAIR							
M PANEL ASSY-HOOD				1.00	1222.00	20.00	977.60
M HINGE ASSY-HOOD,LH				1.00	40.00	20.00	32.00
M HINGE ASSY-HOOD,RH				1.00	40.00	20.00	32.00
M CLIP-HOOD INSULATING PAD MTG				14.00	1.00	20.00	11.20
M LATCH ASSY-HOOD				1.00	123.00	20.00	98.40
M COVER-FR BUMPER UPR				1.00	632.00	20.00	505.60
M CAP-FRONT HOOK				1.00	7.00	20.00	5.60
M COVER ASSY-FR BUMPER LWR				1.00	346.00	20.00	276.80
M PIECE-FRT BUMPER GUARD LWR,LH				1.00	16.00	20.00	12.80
M PIECE-FRT BUMPER GUARD LWR,RH				1.00	16.00	20.00	12.80
M LOGO ASSY-KIA SUB				1.00	51.00	20.00	40.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



CYCLE &amp; CARRIAGE

Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

## Invoice Name &amp; Address

AIG Asia Pacific Insurance Pte.  
Ltd.  
MOTOR CLAIM DEPARTMENT  
78 SHENTON WAY #09-16  
AIG BUILDING  
SINGAPORE 079120  
Contact No 64191000

## Owner Name &amp; Vehicle Info

Cust No/Name / HENG HANN JEN  
Reg No/Reg Date SLM1366C / 22/03/201  
Date In/Mileage / 45113  
Chassis No KNACC81CVH5052717  
Engine No G4LEHS166685  
Make/Model KIA/NIRO 1.6 A  
Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
LAX00000	Credit	08/02/2021/ 11:59	BLE	261 / Edwin Caina	28726				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
M	STRIP ASSY-FR BUMPER UPR	1.00	28.00	20.00		1.00	28.00	20.00	22.40
M	GRILLE ASSY-RADIATOR	1.00	441.00	20.00		1.00	441.00	20.00	352.80
M	COVER ASSY-RADIATOR GRILLE UPR	1.00	40.00	20.00		1.00	40.00	20.00	32.00
M	ABSORBER-FRONT BUMPER ENERGY	1.00	68.00	20.00		1.00	68.00	20.00	54.40
M	GRILLE-FRONT BUMPER	1.00	232.00	20.00		1.00	232.00	20.00	185.60
M	WIRING HARNESS-FR BUMPER	1.00	134.00	20.00		1.00	134.00	20.00	107.20
M	STIFFNER-FR BPR LWR	1.00	116.00	20.00		1.00	116.00	20.00	92.80
M	FLAP ASSY-ACTIVE AIR, LWR	1.00	328.00	20.00		1.00	328.00	20.00	262.40
M	DUCT ASSY-ACTIVE AIR	1.00	78.00	20.00		1.00	78.00	20.00	62.40
M	BRACKET-FR BUMPER SIDE, LH	1.00	12.00	20.00		1.00	12.00	20.00	9.60
M	BRACKET-FR BUMPER SIDE, RH	1.00	12.00	20.00		1.00	12.00	20.00	9.60
M	BEAM COMPLETE-FR BUMPER	1.00	551.00	20.00		1.00	551.00	20.00	440.80
M	CARRIER ASSY-FRONT END MODULE	1.00	675.00	20.00		1.00	675.00	20.00	540.00
M	CONDENSER ASSY-COOLER	1.00	639.00	20.00		1.00	639.00	20.00	511.20
M	RADIATOR ASSY-INVERTER	1.00	768.00	20.00		1.00	768.00	20.00	614.40
M	RADIATOR ASSY	1.00	492.00	20.00		1.00	492.00	20.00	393.60
M	BLOWER ASSY	1.00	546.00	20.00		1.00	546.00	20.00	436.80
M	GUARD-AIR, LH	1.00	29.00	20.00		1.00	29.00	20.00	23.20
M	GUARD-AIR, RH	1.00	29.00	20.00		1.00	29.00	20.00	23.20
M	GUARD-AIR RADIATOR, UPR	1.00	15.00	20.00		1.00	15.00	20.00	12.00
M	LAMP ASSY-HEAD, LH	1.00	904.00	20.00		1.00	904.00	20.00	723.20
M	LAMP ASSY-HEAD, RH	1.00	904.00	20.00		1.00	904.00	20.00	723.20
M	LAMP ASSY-FRONT FOG & DRL, LH	1.00	638.00	20.00		1.00	638.00	20.00	510.40
M	LAMP ASSY-FRONT FOG & DRL, RH	1.00	638.00	20.00		1.00	638.00	20.00	510.40
M	COOLANT (4L)	1.00	26.00	23.00		1.00	26.00	23.00	20.02

SURVEYOR NAME :

SURVEYOR SIGNATURE :

DATE :

Steve CLKK) 8/2/21, 1.00pm

OD- Not AL

EXCISE - ?

P/P

## Confirm &amp; accepted by

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

Nett

13,059.22

13059.22

914.15

Total Payable

13,973.37

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.