

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001857/ETD3E2

Date: 01/04/2021

REFERENCE

Insured/Claimant:	CHEN THIM KWANG	Policy No:	2070106224	
Date of Loss:	07/02/2021	Nature of Claim:	OD	Claim No: 8521441467SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT7211C	Engine No:	3A92UJB1449
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AKH003375
Reg. Date:	15/07/2020 (Man. Year: 2019)	Odometer:	4864 km
Colour:	Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$66,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,899.00	2,109.78	3,789.22	64.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,480.00	5,190.00	1,290.00	19.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,379.00	7,299.78	5,079.22	41.03
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	9,379.00	4,299.78	5,079.22	54.16
+ GST 7.00/7.00% (S\$)	656.53	300.98	355.55	54.16
Nett Amount (S\$)	10,035.53	4,600.76	5,434.77	54.16

INSPECTION

Date of Assignment:	08/02/2021	
Date Inspected:	08/02/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*UNPAINTED BODYKITS	Not Necessary	1,643.00 F	*- FL
3	1		*FACE, RR BUMPER	Dented	751.00 F	*751.00 FL
4	1		*BRACKET, RR BUMPER, RH	Broken	28.00 F	*28.00 FL
5	1		*BRACKET, RR BUMPER, LH	Not Necessary	28.00 F	*- FL
6	1		*PANEL, RR COMB LAMP HSG, RH	Not Necessary	60.00 F	*- FL
7	1		*PANEL, RR COMB LAMP HSG, LH	Not Necessary	60.00 F	*- FL
8	1		*PANEL, RR END	Dented	427.00 F	*427.00 FL
9	1		*PANEL, TRUNK LID	Dented	795.00 F	*795.00 FL
10	1		*WEATHERSTRIP, TRUNK LID	Not Necessary	157.00 F	*- FL
11	1		*HINGE, TRUNK LID, RH	Not Necessary	203.00 F	*- FL
12	1		*HINGE, TRUNK LID, LH	Not Necessary	203.00 F	*- FL
13	1		*LATCH, TRUNK LID	Not Necessary	218.00 F	*- FL
14	1		*GARNISH, RR END PANEL	Not Necessary	336.00 F	*- FL
15	1		*MARK, THREE-DIA	Necessary	70.00 F	*70.00 FL
16	1		*MARK, ATTRAGE	Necessary	21.00 F	*21.00 FL
17	1		*TRIM, RR END	Crushed	66.00 F	*66.00 FL
18	1		*BOARD, TRUNK ROOM FLOOR	Broken	195.00 F	*195.00 FL
19	1		*TRIM, TRUNK ROOM SIDE, RH	Not Necessary	160.00 F	*- FL
20	1		*REFLECTOR	Not Necessary	23.00 F	*- FL
21	1		*REFLECTOR	Not Necessary	23.00 F	*- FL
22	1		*LAMP ASSY, COMB, RR RH	Cracked	337.00 F	*337.00 FL
23	1		*LAMP ASSY, LICENSE PLATE	Not Necessary	51.00 F	*- FL
24	1		*GROMMET (X4) (Supplementary)	Necessary	12.00 F	*12.00 FL
25	1		*CLIPS (X4) (Supplementary)	Necessary	12.00 F	*12.00 FL
					Sub Total (\$)	5,899.00 2,734.00
					- List Item Discount on L Items 0.00/23.00% (\$)	0.00 624.22
					Total Parts (\$)	5,899.00 2,109.78

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER, BOOTLID, REAR LAMP HOUSING RH, REAR END PANEL, REAR AIRDAM, REPAIR REAR FENDER LH, REAR COMPARTMENT, REAR FENDER RH	New	2,250.00	2,250.00
2	REMOVE & INSTALL REAR AIR DAM	New	100.00	80.00
3	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
4	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	300.00	300.00
5	SPRAY PAINTN FOR REAR AIRDAM, REAR BUMPER, REAR END PANEL, BOOT LID, REAR COMPARTMENT, REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH	New	3,150.00	2,100.00
6	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	80.00
9	C&C LOGO	New	40.00	40.00
10	SUPPLY PARKING SENSOR	New	220.00	0.00
11	SUPPLY & REPLACE REAR LICENSE WITH FRAME (Supplementary)	New	50.00	50.00
12	APPLICATION TO BREAK REAR OPC PLATE AT LTA, AND RESEAL AT VICOM (Supplementary)	New	80.00	80.00
Gross Labour Cost (\$\$)			6,480.00	5,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >