



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (S) PTE LTD

INV No. AC2202780

1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV Date 17/05/2022
Reference CC6/QBE21001860/Uea3q2
Code QBE

PROFESSIONAL SERVICE FEE

Vehicle No. SME 3570X
Insured Veh. SCG 28Z
Claim No. VC014307
Policy No. 2020-V0026194-MVA
Accident Date 06/02/2021
Inspection Date 08/02/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (S) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Ref: CC6/QBE21001860/Uea3q2	
			Date: 17/05/2022	
			Code: QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCG 28Z	Veh. Inspected	SME 3570X	
Policy No.	2020-V0026194-MVA	Coverage (\$)	0.00	
Claim No.	VC014307	Excess (\$)	0.00	
Assign From		Assign Date	08/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C 180 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WDD2040312A888587	Colour	BLACK	
Odometer	118845 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	MICHELIN	6 mm	
L/H Front Tyre	225/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/02/2021	Inspection Date	08/02/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 3570X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	2,021.32	-
1	FRONT BUMPER PDC SENSOR N/S	NOT NECESSARY	225.00	-
1	FRONT BUMPER SIDE RETAINER N/S	NOT NECESSARY	68.50	-
1	SET FRONT BUMPER CLIPS	TO REPAIR SEE LABOUR	50.00	-
2	FRONT BUMPER LOWER CHROME MOULDING @\$118.00	TO REPAIR SEE LABOUR	236.00	-
1	HEADLAMP N/S	TO REPAIR SEE LABOUR	2,850.00	-
1	FRONT FENDER N/S	TO REPAIR SEE LABOUR	912.30	-
1	FRONT FENDER LOWER CHROME MOULDING N/S	TO REPAIR SEE LABOUR	102.00	-
1	FRONT SPORT RIM N/S	TO REPAIR SEE LABOUR	1,450.00	-
	LESS 10% DISCOUNT		-	-
			7,915.12	-
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REFIX FRONT PDC SENSOR .		80.00	50.00
	TO SPRAY RUST PROOFING .	NOT NECESSARY	50.00	-
	TO CONDUCT WHEEL ALIGNMENT .		120.00	80.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER,SET FRONT BUMPER CLIPS,FRONT BUMPER LOWER CHROME MOULDING,HEADLAMP N/S,FRONT FENDER N/S,FRONT FENDER LOWER CHROME MOULDING N/S AND FRONT SPORT RIM N/S .		580.00	300.00
	TO PUTTY & SPRAY PAINTING .		680.00	500.00
			1,560.00	950.00
	GRAND TOTAL		9,475.12	950.00

Report Ref No. CC6/QBE21001860/Uea3q2



RECOMMENDED COST OF REPAIRS			950.00
-----------------------------	--	--	--------

Report Ref No. CC6/QBE21001860/Uea3q2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 3570X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 3570X

RE-INSPECTION

