

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21001862/KQF3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001622415

Claimant

Vehicle No : SJJ5806M

Insured Vehicle No : SLN8801L

Date of Loss: 04/02/2021

Nature of Claim: TP

Claim No: 253115

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ5806M**

Make & Model: MERCEDES-BENZ C180K, 1.6 (A)

Engine No: 27195231087651

Reg. Date: 19/09/2008 (Man. Year: 2008)

Chassis No: WDD2040462A174703

Colour: Metallic Silver

Odometer: 237577 km

Engine Capacity: 1597 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Hankook 7 mm

Rear Left Side:

Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side:

Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|---|------------------|-----------------|------------------|--------------|
| Parts | 8,618.50 | 1,872.00 | 6,746.50 | 78.28 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,310.00 | 575.00 | 2,735.00 | 82.63 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$) | 11,928.50 | 2,447.00 | 9,481.50 | 79.49 |
| Approved Total (Overridden) (\$) | | 1,950.00 | | |
| (S\$) | 11,928.50 | 1,950.00 | 9,978.50 | 83.65 |
| + GST 7.00/7.00% (S\$) | 835.00 | 136.50 | 698.50 | 83.65 |
| Nett Amount (S\$) | 12,763.50 | 2,086.50 | 10,677.00 | 83.65 |

INSPECTION

Date of Assignment: 08/02/2021

Date Inspected: 22/02/2021 Inspected At:

MBM Wheelpower Pte Ltd (HQ)
160 Sin Ming Drive #06-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 12 Mar 2021) |
| Parts: | 143 | MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJJ5806M) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|----------------------------------|-----------------------|--|--------------------------|
| 1 | 1 | *BOOTLID | Repair | 1,900.00 FL | *- FL |
| 2 | 1 | *BOOTLID WEATHERSTRIP | Serviceable | 200.00 FL | *- FL |
| 3 | 1 | *BOOTLID HINGE LH | Repair | 650.00 FL | *- FL |
| 4 | 1 | *BOOTLID HINGE RH | Repair | 650.00 FL | *- FL |
| 5 | 1 | *BOOTLID LOCK | Repair | 350.00 FL | *- FL |
| 6 | 1 | *BOOT LID MERCEDES LOGO | Not Necessary | 55.00 FL | *- FL |
| 7 | 1 | *TAIL LAMP LH | Serviceable | 600.00 FL | *- FL |
| 8 | 1 | *TAIL LAMP RH | Serviceable | 600.00 FL | *- FL |
| 9 | 1 | *REAR BUMPER | Buckled | 1,600.00 FL | *1,345.00 FL |
| 10 | 1 | *REAR BUMPER RETAINER LH | Distorted | 75.00 FL | *75.00 FL |
| 11 | 1 | *REAR BUMPER RETAINER LH | Serviceable | 75.00 FL | *- FL |
| 12 | 1 | *REAR BUMPER REINFORCEMENT | Repair | 750.00 FL | *- FL |
| 13 | 1 | *REAR BUMPER SENSOR 4 Pcs | Scratched (1 pc only) | 1,000.00 FL | *250.00 FL |
| 14 | 10 | *REAR BUMPER CLIP | Necessary | 90.00 FL | *60.00 FL |
| 15 | 1 | *REAR BUMPER CHROME STRIP CENTER | Necessary | 120.00 FL | *120.00 FL |
| 16 | 1 | *REAR BUMPER CHROME STRIP LH | Necessary | 120.00 FL | *115.00 FL |
| 17 | 1 | *REAR BUMPER CHROME STRIP RH | Necessary | 120.00 FL | *115.00 FL |
| 18 | 1 | *REAR BUMPER TOWING COVER | Serviceable | 60.00 FL | *- FL |
| 19 | 2 | *EXHAUST PIPE TIP | Serviceable | 450.00 FL | *- FL |
| 20 | 1 | *REAR NUMBER PLATE & HOLDER | Serviceable | 50.00 FS | *- FS |
| 21 | 1 | *BODY SEALANT | Serviceable | 50.00 FS | *- FS |
| | | | | Sub Total (\$\$) | 9,565.00 2,080.00 |
| | | | | - List Item Discount on L Items 10.00/10.00% (\$\$) | 946.50 208.00 |
| | | | | Total Parts (\$\$) | 8,618.50 1,872.00 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS,INCLUDING TO KNOCK-OUT,WELD & STRAIGHTEN ON THE AFFECTED PARTS | New | 1,600.00 | 250.00 |
| 2 | TO CHECK & RECONNECT ALL NECESSARY WIRING | New | 150.00 | 15.00 |
| 3 | TO REMOVE & REFIT ALL SENSOR | New | 100.00 | 60.00 |
| 4 | TO REALIGN EXHAUST PIPE | New | 80.00 | 0.00 |
| 5 | TO RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC) | New | 100.00 | 0.00 |
| 6 | TO APPLY ANTI RUST COATING | New | 80.00 | 0.00 |
| 7 | TO SPRAY PAINT ON THE AFFECTED AREAS | New | 1,200.00 | 250.00 |
| Gross Labour Cost (\$\$) | | | 3,310.00 | 575.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >