

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21001864/UGA3Q2**Date:** 18/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : JDD72 **Insured Vehicle No :** SLP9162E
 Date of Loss: 02/02/2021 Nature of Claim: TP Claim No: MFL2021D0000585

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **JDD72**
 Make & Model: YAMAHA 135LC, 135cc ES Engine No: G3G5E107858
 Reg. Date: 16/07/2019 (Man. Year: 2019) Chassis No: PMYUG0810K0107818
 Colour: Black Odometer: 0 km
 Engine Capacity: 134 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90-17 Rear Tyre Size: 80/90-17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,549.10	2,002.90	1,546.20	43.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	250.00	680.00	73.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,479.10	2,252.90	2,226.20	49.70
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	4,479.10	1,800.00	2,679.10	59.81
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
Nett Liability (S\$)		1,920.00		

INSPECTION

Date of Assignment: 08/02/2021
 Date Inspected: 08/02/2021 Inspected At: Erofia Motor Trading Pte Ltd (KAKI BUKIT)
 1 KAKI BUKIT AVE 6 #02-62
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Aug 2021)	
Parts:	N/A	YAMAHA 135LC 135cc ES (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JDD72)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK TUBE ASSY	N/S Twisted	640.00 FL	*295.00 FL
2	1		*FRONT WHEEL RIM	Cut / Bent	380.00 FL	*305.00 FL
3	1		*FORK UNDER BRACKET	Bent	185.00 FL	*160.00 FL
4	1		*FRONT RIM SHAFT	Cut	45.00 FL	*35.00 FL
5	1		*FRONT RIM BEARING	Necessary	38.00 FL	*38.00 FL
6	1		*FRONT BRAKE DISC	Bent	165.00 FL	*145.00 FL
7	1		*HANDLE BAR	Bent	88.00 FL	*88.00 FL
8	1		*HANDLE BAR ENDS	N/S Cut	78.00 FL	*35.00 FL
9	1		*SET HAND GRIP	Not Necessary	55.00 FL	*- FL
10	2		*SIDE MIRRORS	Not Necessary	110.00 FL	*- FL
11	1		*BRAKE LEVER	Not Necessary	32.00 FL	*- FL
12	1		*SET FAIRING ASSY	Cut / Cracked	525.00 FL	*465.00 FL
13	1		*FRONT FOOTREST BRACKET	Bent	65.00 FL	*65.00 FL
14	1		*FRONT FOOTREST RUBBERS	N/S Torn	70.00 FL	*30.00 FL
15	1		*GEAR PEDAL	Cut	42.00 FL	*42.00 FL
16	2		*REAR FOOTREST	Serviceable	80.00 FL	*- FL
17	2		*REAR FOOTREST BRACKETS	Not Necessary	156.00 FL	*- FL
18	1		*REAR FENDER	Distorted	180.00 FL	*140.00 FL
19	1		*REAR SIGNALS	N/S Broken	140.00 FL	*68.00 FL
20	1		*SIDE STAND	Not Necessary	70.00 FL	*- FL
21	1		*MAIN STAND	Not Necessary	95.00 FL	*- FL
22	1		*TAILLAMP (NPA)	Not Necessary	0.00 FL	*- FL
23	1		*HEADLAMP (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*SET NUMBER PLATE	Rear Bent	28.00 FS	*10.00 FS
25	1		*FORK OILS	N/S Necessary	30.00 FS	*15.00 FS
26	1		*FORK OIL SEALS	N/S Necessary	56.00 FS	*28.00 FS
27	1		*SET STEERING CONE	Necessary	90.00 FS	*50.00 FS
28	1		*REAR BOX	Cut	280.00 FS	*180.00 FS
29	1		*REAR BOX BRACKET	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,873.00	2,194.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	323.90	191.10
Total Parts (\$\$)	3,549.10	2,002.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	50.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	420.00	250.00
4	TO REPAIR BODY FRAME	New	380.00	0.00
Gross Labour Cost (\$\$)			930.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >