

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21001865/ABS3Q2
Date: 10/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMR814U	Insured Vehicle No :	SLP9832E
Date of Loss:	06/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000738

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR814U		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	2NR5394841
Reg. Date:	18/12/2019 (Man. Year: 2019)	Chassis No:	MR2B23F3701189738
Colour:	Grey	Odometer:	22804 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,198.77	1,349.10	849.67	38.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	530.00	470.00	47.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,198.77	1,879.10	1,319.67	41.26
Approved Total (Overridden) (\$\$)		1,500.00		
(\$\$)	3,198.77	1,500.00	1,698.77	53.11
+ GST 7.00/7.00% (\$\$)	223.91	105.00	118.91	53.11
Nett Amount (\$\$)	3,422.68	1,605.00	1,817.68	53.11
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	08/02/2021	
Date Inspected:	09/02/2021	Inspected At: Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2021)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR814U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Deformed	498.50 FL	*498.50 FL
2	5		*FRT BUMPER CLIPS	Necessary	28.90 FL	*28.90 FL
3	1		*FRT BUMPER SIDE HOLER RH	Necessary	100.80 FL	*38.00 FL
4	1		*FRT BUMPER LOWER AIR GRILLE	Not Necessary	269.50 FL	*- FL
5	1		*FRT BUMPER FOGLAMP GARNISH RH	Cut	88.50 FL	*88.50 FL
6	1		*FRT BUMPER REINFORCEMENT	Not Necessary	399.50 FL	*- FL
7	1		*HEADLAMP ASSY	Cut	1,144.90 FL	*1,144.90 FL
8	1		*HEADLAMP BRACKET RH	Not Necessary	79.80 FL	*- FL
9	1		*FRT GRILLE ASSY	Not Necessary	321.30 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,931.70	1,798.80
- List Item Discount on L Items 25.00/25.00% (\$)	732.93	449.70
Total Parts (\$)	2,198.77	1,349.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	50.00	30.00
2	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	400.00	300.00
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	550.00	200.00
Gross Labour Cost (S\$)			1,000.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >