

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21001867/KVF3Q2
Date: 05/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070116590
Claimant Vehicle No :	SMM5830R	Insured Vehicle No :	SMU2962X
Date of Loss:	07/02/2021	Nature of Claim:	TP
		Claim No:	4863973586SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM5830R	Engine No:	L13Z11022091
Make & Model:	HONDA JAZZ, 1.3 L (A)	Chassis No:	JHMGE68509S222089
Reg. Date:	14/07/2009 (Man. Year: 2008)	Odometer:	135678 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Tourador 8 mm	Rear Left Side:	Tourador 8 mm
Front Right Side:	Tourador 8 mm	Rear Right Side:	Tourador 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,488.48	2,561.60	1,926.88	42.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,520.00	1,120.00	42.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,128.48	4,081.60	3,046.88	42.74
Approved Total (Overridden) (S\$)		3,250.00		
Nett Amount (S\$)	7,128.48	3,250.00	3,878.48	54.41

INSPECTION

Date of Assignment:	08/02/2021		
Date Inspected:	17/02/2021	Inspected At:	Massive Trading & Auto Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2 Singapore 569541
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE ASSY	Bent	788.60 FL	*771.50 FL
2	1		*REAR TAIL-GATE EMBLEM JASS	Necessary	48.30 FL	*48.30 FL
3	1		*REAR TAIL-GATE OUTER HANDLE	Serviceable	185.60 FL	*- FL
4	1		*REAR WIPER MOTOR	Serviceable	325.65 FL	*- FL
5	1		*REAR TAIL-GATE INNER LOCK	Dented	205.20 FL	*205.20 FL
6	1		*REAR TAIL-GATE GLASS MOULDING	Necessary	95.70 FL	*95.70 FL
7	1		*REAR TAIL-GATE INNER TRIM BOARD	Mtg Cracked	255.70 FL	*255.70 FL
8	2		*REAR NO PLATE LAMP	Serviceable	97.40 FL	*- FL
9	1		*REAR TAIL-LAMP ASSY	N/s Cut	510.20 FL	*255.10 FL
10	1		*REAR END PANEL	Bent	296.80 FL	*296.80 FL
11	1		*REAR END PANEL INNER GARNISH	Mtg Distorted	80.20 FL	*80.20 FL
12	1		*REAR FENDER INNER TRIM BOARD	N/s Cracked/O/s Serviceable	527.80 FL	*263.90 FL
13	1		*REAR BOOT RUBBER	Serviceable	105.20 FL	*- FL
14	1		*REAR BUMPER	Buckled	486.20 FL	*474.50 FL
15	1		*REAR BUMPER SIDE RETAINER	N/s Distorted	110.20 FL	*55.10 FL
16	2		*REAR BUMPER BRACKETS	Serviceable	71.20 FL	*- FL
17	1		*REAR BUZZER	Serviceable	105.10 FL	*- FL
18	1		*REAR EXHAUST SILENCER	Repair	546.80 FL	*- FL
19	1		*REAR NO PLATE	Dented	40.00 FS	*40.00 FS
20	1		*REAR WINDSCREEN SEALANT	Necessary	55.00 FS	*40.00 FS
21	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
22	1		*REAR REVERSE CAMERA	Serviceable	280.00 FS	*- FS
23	20		*BUMPER CLIP	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,456.85	3,122.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	968.37	560.40
Total Parts (\$\$)	4,488.48	2,561.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	1,000.00	600.00
2	TO PUTTY & RESPRAY ON REAR ACCIDENT AFFECTED PORTION	New	1,000.00	600.00
3	CHECK/RECONNECT WIRING	New	30.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	120.00	60.00
5	REMOVE/REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
6	REMOVE/REFIT REAR TAIL-GATE MECHANISM,TRIM BOARD TO NEW DOOR	New	100.00	60.00
7	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00	60.00
8	REMOVE/RENEW REAR EXHAUST SILENCER	New	150.00	0.00
Gross Labour Cost (\$\$)			2,640.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >