



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD (SMQ9823P)
Date of Loss	5 February 2021
Time of Loss	18:30
Loss Description	SHC1450S (INSD) rear-end SMQ9823P (TP)
Comment	<input type="text"/>

Workshop Details

Total Rebate
Amount

0

Nett Loss Amount

-\$43,249.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work
completion *

20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SMQ9823P

Registration State

SINGAPORE

Mileage

13276

Purchase Date

DD/MM/YYYY



Registration Date *

13/12/2019



Age of Vehicle

1

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2019

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION





Driver Name

TAN TUAN WEI
IVAN

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD	<input type="text" value="TOYOTA"/>
Model		<input type="text" value="COROLLA ALTIS ELEGA"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="MR2BE3BE400004873"/>
Engine No		<input type="text" value="1ZR0E86160"/>
Engine Capacity		<input type="text" value="1598"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		<input type="text" value="DD/MM/YYYY"/> 
Age	0	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value=""/> 
Gender	Unknown	<input type="text" value=""/> 
Marital status	Unknown	<input type="text" value=""/> 
Identification #	TBC	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

09/02/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

225/45R17

Front left side

DUNLOP6mm

Front right side

DUNLOP6mm

Spare wheel

Rear Tyre Size

225/45R17

Rear left side

DUNLOP6mm

Rear right side

DUNLOP6mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

25

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio












Parts & Labour






Miscellaneous












Summary




Parts

Add		Approve		Deny		Submit All							
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		BOOTLID	Bent	0	912	No	0	25	0	0	684
	0	1		BOOTLID WEATHERSTRIPE	Twisted	0	175	No	0	25	0	0	131.25
	0	1		BOOTLID LOGO	Necessary	0	68	No	0	25	0	0	51
	0	1		BOOTLID EMBLEM "COROLLA"	Necessary	0	59	No	0	25	0	0	44.25
	0	1		BOOTLID EMBLEM "ALTIS"	Necessary	0	59.9	No	0	25	0	0	44.93
	0	1		BOOTLID CHROME GARNISH	Serviceable	0	0	No	0	0	0	0	0
	0	2		BOOTLID LAMP	Serviceable	0	0	No	0	0	0	0	0
	0	2		BOOTLID LAMP CHROME	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		BOOTLID REVERSE CAMERA	Serviceable	0	0	No	0	0	0	0	0
	0	1		BOOTLID INNER TRIM	Serviceable	0	0	No	0	0	0	0	0
	0	11		BOOTLID INNER TRIM CLIPS	Serviceable	0	0	No	0	0	0	0	0
	0	2		BOOTLID HINGE	Repair	0	0	No	0	0	0	0	0
	0	2		BOOTLID STOPPER	Serviceable	0	0	No	0	0	0	0	0
	0	1		BOOTLID LOCK	Bent	0	256.4	No	0	25	0	0	192.3
	0	1		BOOTLID STRIKER	Repair	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER	Cracked	0	537.1	No	0	25	0	0	402.83
	0	10		REAR BUMPER CLIPS	Necessary	0	3	No	0	25	0	0	22.5
	0	1		REAR BUMPER SIDE ATTACHMENT N/S	Deformed	0	121.8	No	0	25	0	0	91.35
	0	1		REAR BUMPER SIDE ATTACHMENT O/S	Serviceable	0	0	No	0	0	0	0	0















EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BUMPER REFLECTOR N/S	Cracked	0	156	No	0	25	0	0	117
	0	1		REAR BUMPER REFLECTOR O/S	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER LOWER COVER	Deformed	0	286	No	0	25	0	0	214.5
	0	1		REAR BUMPER LOWER COVER CLIPS (8PCS)	Necessary	0	17.8	No	0	25	0	0	13.35
	0	1		REAR BUMPER REINFORCEMENT	Bent	0	316	No	0	25	0	0	237
	0	1		REAR ANTENNA SENSOR	Serviceable	0	0	No	0	0	0	0	0
	0	1		END PANEL	Bent	0	468	No	0	25	0	0	351
	0	1		END PANEL TOP GARNISH COVER	Deformed	0	58	No	0	25	0	0	43.5
	0	1		END PANEL TOP GARNISH	Deformed	0	205.6	No	0	25	0	0	154.2
	0	8		END PANEL TOP GARNISH CLIPS	Necessary	0	8.9	No	0	25	0	0	53.4
	0	1		SPARE TYRE PANEL	Bent	0	708	No	0	25	0	0	531
	0	1		SPARE TYRE BOARD	Serviceable	0	0	No	0	0	0	0	0









EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		TAIL LAMP (LH)	Cut	0	422.5	No	0	25	0	0	316.88
	0	1		TAIL LAMP CLIP N/S	Necessary	0	8.9	No	0	25	0	0	6.68
	0	1		TAIL LAMP CLIP O/S	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAIL LAMP LOWER BRACKET (LH)	Cracked	0	185	No	0	25	0	0	138.75
	0	1		REAR FENDER N/S	Repair	0	0	No	0	0	0	0	0
	0	1		REAR FENDER O/S	Serviceable	0	0	No	0	0	0	0	0
	0	2		REAR FENDER INNER SHIELD	Serviceable	0	0	No	0	0	0	0	0
	0	16		REAR FENDER INNER SHIELD CLIPS	Serviceable	0	0	No	0	0	0	0	0
	0	2		REAR FENDER INNER TRIM	Serviceable	0	0	No	0	0	0	0	0
	0	20		REAR FENDER INNER TRIM CLIPS	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BLIND SPOT SENSOR (LH)	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	2		REAR CHASSIS MEMBER	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR SIDE PANEL EXTENSION N/S	Repair	0	0	No	0	0	0	0	0
	0	1		REAR SIDE PANEL EXTENSION O/S	Serviceable	0	0	No	0	0	0	0	0

Labour

Add	Approve	Deny	Submit All
-----	---------	------	------------

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO CHECK WIRING SYSTEM	0	30	0	0	Reviewing		
	0		TO APPLY UNDER SEALING ON AFFECTED AREAS	0	40	0	0	Reviewing		
	0		TO MOUNT VEHICLE ON CAR O-LINER	0	0	0	0	Deny		
	0		TO REMOVE & REFIX REAR WINDSCREEN	0	0	0	0	Deny		
	0		TO REMOVE & REFIX BOOT LID FIXING AND REALIGNMENT	0	60	0	0	Reviewing		
	0		TO REMOVE & REFIX REVERSE CAMERA	0	30	0	0	Reviewing		
	0		TO REMOVE & REFIX REVERSE SENSOR & REPROGRAMME	0	30	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO REMOVE & REFIX PETROL TANK, PIPING, BRACKET ETC TO FACILITATE REPAIR	0	0	0	0	Deny		
	0		TO REMOVE / REFIX CUSHION, FLOOR BOARD, ROOF LINING, TRIM GARNISH, UPHOLSTERY ETC	0	60	0	0	Reviewing		
	0		TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC	0	800	0	0	Reviewing		
	0		TO RESPRAY ON AFFECTED AREAS	0	900	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition



Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 7 DAYS	Reviewing	0	0		
	0	END PANEL SEALANT	Reviewing	0	55	NECESSARY	
	0	REAR WINDSCREEN GUM	Deny	0	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR WINDSCREEN INNER SEAL	Deny	0	0	NOT NECESSARY	
	0	REAR FENDER SEALANT	Deny	0	0	NOT NECESSARY	
	0	SPARE TYRE INSULATOR CLOTH	Deny	0	0	NOT NECESSARY	
	0	SPARE TYRE PANEL SEALANT	Deny	0	0	NOT NECESSARY	
	0	1 SET REAR BUMPER REVERSE SENSOR	Reviewing	0	200	NOT WORKING	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$6,046.67
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$3,841.67
Labour	\$0.00	\$1,950.00
Miscellaneous	\$0.00	\$255.00

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

4850





Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$4,850.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$4,850.00

Submit for Review