

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21001874/ARS3Q2
Date: 10/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900245464
Claimant Vehicle No :	SKQ6377D	Insured Vehicle No :	SLA7097C
Date of Loss:	05/02/2021	Nature of Claim:	TP
		Claim No:	3803188575SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ6377D		
Make & Model:	RENAULT CAPTUR, 1.5 D T dCi (A)	Engine No:	K9KD609D023463
Reg. Date:	16/12/2014 (Man. Year: 2014)	Chassis No:	VF12REL1E51557079
Colour:	Grey	Odometer:	165221 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

1/10/22, 2:21 PM

Adjuster Report

Date of Assignment: 08/02/2021

Date Inspected: 09/02/2021

Estimated Period of Repair: 18.0 days

Inspected At:

Tridente Automobili Pte Ltd (HQ)
30 Leng Kee Road #01-02
Singapore 159100

Adjuster: ADRIAN LING

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$42,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE HOLDER	Bent	0.00 F	*- F
3	2		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*- F
4	1		*REAR BUMPER	Dented	0.00 F	*- F
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
6	2		*REAR BUMPER SIDE HOLDER	Distorted	0.00 F	*- F
7	2		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
8	1		*REAR BUMPER TOW COVER	Dented	0.00 F	*- F
9	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
10	1		*REAR BUMPER REINFORCEMENT COVER	Cracked	0.00 F	*- F
11	1		*REAR BUMPER CENTRE GUIDE	Dented	0.00 F	*- F
12	1		*REVERSE SENSOR	Cut	0.00 F	*- F
13	1		*REAR END PANEL	Buckled	0.00 F	*- F
14	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
15	2		*REAR END PANEL AIR DUCT	Distorted	0.00 F	*- F
16	2		*TAILLAMP	Cracked	0.00 F	*- F
17	2		*TAILLAMP LOWER BRACKET	Bent	0.00 F	*- F
18	2		*TAILLAMP LOWER APRON	Distorted	0.00 F	*- F
19	1		*TAILGATE	Buckled	0.00 F	*- F
20	1		*TAILGATE LOCK	Bent	0.00 F	*- F
21	1		*TAILGATE WEATHERSTRIPE	Torn	0.00 F	*- F
22	1		*TAILGATE OUTER CHROME	Cracked	0.00 F	*- F
23	2		*TAILGATE REFLECTOR	Cracked	0.00 F	*- F
24	1		*TAILGATE INNER TRIM	Cracked	0.00 F	*- F
25	1		*TAILGATE INNER TRIM CLIPS	Necessary	0.00 F	*- F
26	1		*TAILGATE DAMPER	Bent	0.00 F	*- F
27	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
28	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
29	1		*RENAULT LOGO	Necessary	0.00 F	*- F
30	1		*DCI EMBLEM	Necessary	0.00 F	*- F
31	2		*REAR FENDER	Buckled	0.00 F	*- F
32	2		*REAR FENDER INNER TRIM BOARD	Cracked	0.00 F	*- F
33	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	0.00 F	*- F
34	2		*REAR FENDER INNER SHIELD	Torn	0.00 F	*- F
35	1		*REAR FENDER INNER SHIELD CLIPS	Necessary	0.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*REAR FENDER GLASS MOULDING	Necessary	0.00 F	*- F
37	2		*REAR FENDER GLASS SEALANT	Necessary	0.00 F	*- F
38	1		*REAR EXHAUST PIPE	Bent	0.00 F	*- F
39	1		*REAR EXHAUST HEAT SHIELD	Distorted	0.00 F	*- F
40	1		*REAR LH WHEEL HOUSING PANEL	Buckled	0.00 F	*- F
41	1		*SPARE TYRE PANEL	Buckled	0.00 F	*- F
42	2		*SPARE TYRE PANEL SIDE	Buckled	0.00 F	*- F
43	1		*SPARE TYRE PANEL INSULATION PAD	Necessary	0.00 F	*- F
44	1		*SPARE TYRE PANEL TOP COVER	Torn	0.00 F	*- F
45	1		*REAR LH DOOR	Buckled	0.00 F	*- F
46	1		*REAR LH DOOR LOCK	Bent	0.00 F	*- F
47	1		*REAR LH DOOR WEATHERSTRIPE	Torn	0.00 F	*- F
48	1		*REAR AXLE	Bent	0.00 F	*- F
49	2		*REAR AXLE BEARING	Necessary	0.00 F	*- F
50	2		*REAR SHOCK ABSORBER	Bent	0.00 F	*- F
51	2		*REAR CHASSIS MEMBER	Repair	0.00 F	*- F
52	1		*CENTRE EXHAUST PIPE	Repair	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00
						0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >