

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 6843M

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER (CONSISTENT) | TO REPAIR SEE LABOUR | 1,265.70 | - |
| 1 | REAR BUMPER SIDE RETAINER (CONSISTENT) | SERVICEABLE | 76.00 | - |
| 1 | REAR LOWER ARM (CONSISTENT) | DISTORTED | 216.80 | 216.80 |
| 1 | REAR TRAILING ARM (CONSISTENT) | DISTORTED | 256.20 | 256.20 |
| 1 | REAR KNUCKLE ARM (CONSISTENT) | BENT | 498.50 | 498.50 |
| 1 | WHEEL HUB WITH BEARING(CONSISTENT) | NECESSARY | 521.80 | 521.80 |
| 1 | REAR ANTI ROLL BAR (CONSISTENT) | SERVICEABLE | 386.30 | - |
| 1 | REAR ANTI ROLL BAR LINKAGE (CONSISTENT) | SERVICEABLE | 123.80 | - |
| 1 | ALLOY RIM (CONSISTENT) | DENTED | 985.70 | 985.70 |
| 1 | OUTPUT SHAFT (CONSISTENT) | TO REPAIR SEE LABOUR | 2,380.90 | - |
| | LESS 10% DISCOUNT | | - | -247.90 |
| | | | 6,711.70 | 2,231.10 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET BILSTEIN B 12 SHOCK ABSORBER (MODIFIED) (CONSISTENT) (SN) | BENT | 2,250.00 | 1,800.00 |
| | | | 2,250.00 | 1,800.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE ,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF REAR BUMPER AND OUTPUT SHAFT . | | 600.00 | 200.00 |
| | TO SPRAY PAINTING ON AFFECTED AREAS . | | 680.00 | 400.00 |
| | TO REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS. | | 360.00 | 200.00 |
| | 4 WHEEL COMPUTERISED ALIGNMENT. | | 85.00 | 60.00 |
| | TO REPLACE ALLOY RIM AND BALANCE WHEEL . | | 50.00 | 20.00 |
| | | | 1,775.00 | 880.00 |
| | GRAND TOTAL | | 10,736.70 | 4,911.10 |

Report Ref No. CC4/ASM21001877/Kgs3q2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 3,900.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | · |

Report Ref No. CC4/ASM21001877/Kgs3q2

KONG SENG CHEONG

Licensed Appraiser