

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM21001877/Kgs3q2
	8 SHENTON WAY AXA TOWERSING			Date:	17/06/2021
	ATTN:VALE OH			Code:	ASM
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SFK 2553D	Veh. Inspected		SKE 6843M
	Policy No.	GA143255/1	Coverage (\$)		0.00
	Claim No.	S1M032DA	Excess (\$)		0.00
	Assign From		Assign Date		08/02/2021
2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 318I (A)	c.c		1997
	Engine No.	HIDDEN	Year of Reg.		2012
	Chassis No.	WBA3A52050F253619	Colour		METALLIC BLACK
	Odometer	108490 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	245/35 R19	BRIDGESTONE		7 mm
	L/H Front Tyre	245/35 R19	BRIDGESTONE		7 mm
	R/H Rear Tyre	275/30 R19	BRIDGESTONE		7 mm
	L/H Rear Tyre	275/30 R19	BRIDGESTONE		7 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION AND UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	06/02/2021	Inspection Dat	е	22/02/2021
	Survey held at	SUPREME AUTO SERVICE PTE	LTD		
		176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
·					