

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001879/EVF3Q2

Date: 09/03/2021

REFERENCE

Insured/Claimant:	YEAP HOOI KEA	Policy No:	1900153043	
Date of Loss:	08/02/2021	Nature of Claim:	OD	Claim No: 3527720713SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN9358G			
Make & Model:	KIA STONIC, 998cc (A)	Engine No:	G3LCKP112184	
Reg. Date:	03/09/2019 (Man. Year: 2019)	Chassis No:	KNAD6811VL6347613	
Colour:	Yellow	Odometer:	27849 km	
Engine Capacity:	998 cc			
Market Value/New Car Price:	S\$77,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R17	Rear Tyre Size:	205/55R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,481.00	1,032.80	448.20	30.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,720.00	600.00	25.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,801.00	2,752.80	1,048.20	27.58
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	3,401.00	2,352.80	1,048.20	30.82
+ GST 7.00/7.00% (S\$)	238.07	164.70	73.37	30.82
Nett Amount (S\$)	3,639.07	2,517.50	1,121.57	30.82

INSPECTION

Date of Assignment: 08/02/2021

Date Inspected: 09/02/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-REAR DOOR,RH	Dented	768.00 F	*768.00 FL
2	1		*TAPE-RR DR BLACK FRAME FR,RH	Necessary	13.00 F	*13.00 FL
3	1		*BLACK TAPE-RR DR FRAME UPR,RH	Necessary	7.00 F	*7.00 FL
4	1		*TAPE-RR DR FRAME BLACK RR,RH	Necessary	6.00 F	*6.00 FL
5	1		*MOULDING ASSY-SIDE SILL,RH	Cut	248.00 F	*248.00 FL
6	1		*GARNISH ASSY-FR DR SIDE RH	Cut	82.00 F	*82.00 FL
7	1		*GARNISH ASSY-RR DR SIDE RH	Cut	92.00 F	*92.00 FL
8	1		*GARNISH-QTR SIDE RH	Cut	50.00 F	*50.00 FL
9	1		*REGULATOR ASSY-FR DR WDO RH	Not Necessary	195.00 F	*- FL
10	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,481.00	1,286.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	253.20
Total Parts (\$)	1,481.00	1,032.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW REAR DOOR RH,SIDE SILL RH,REPAIR FRT DOOR RH	New	1,200.00	600.00
2	REMOVE & INSTALL REAR DOOR TRIMS AND GLASS	New	150.00	150.00
3	SPRAY PAINT FOR FRT DOOR RH,REAR DOOR RH	New	700.00	700.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
7	REMOVE & INSTALL RH SIDE SILL (Supplementary)	New	80.00	80.00
Gross Labour Cost (\$\$)			2,320.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >