

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21001883/GBA3Q2
Date: 16/06/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLT5328A	Insured Vehicle No :	SLP8997U
Date of Loss:	05/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000530

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT5328A		
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Engine No:	FB20Y251137
Reg. Date:	31/05/2016 (Man. Year: 2016)	Chassis No:	JF1SJ5KC5GG070412
Colour:	Silver	Odometer:	79130 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,782.30	2,625.44	3,156.86	54.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,865.00	4,985.00	5,880.00	54.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,647.30	7,610.44	9,036.86	54.28
+ GST 7.00/7.00% (S\$)	1,165.31	532.73	632.58	54.28

Nett Amount (S\$)	17,812.61	8,143.17	9,669.44	54.28
+ Car Rental (9.0 x S\$110.00/day + 7.00% GST) (S\$)		1,059.30		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,209.92		

INSPECTION

Date of Assignment: 08/02/2021

Date Inspected: 24/02/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Motor Image Enterprises Pte Ltd (HQ)
 19 LORONG 8 TOA PAYOH
 Singapore 319255

Adjuster: XING GUO QIANG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2021)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT5328A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GLASS -REAR GATE	Necessary	799.20 F	*799.20 FL
2	1		*RUBBER -REAR GATE	Necessary	12.60 F	*12.60 FL
3	2		*DAM RUBBER -REAR GATE GLASS	Necessary	7.20 F	*7.20 FL
4	1		*PANEL -REAR GATE	Buckled	1,072.80 F	*1,072.80 FL
5	1		*LATCH & ACTUATOR -REAR GATE	Not Necessary	144.00 F	*- FL
6	1		*STRIKER -REAR GATE	Not Necessary	21.60 F	*- FL
7	1		*WEATHERSTRIP -REAR GATE	Not Necessary	111.60 F	*- FL
8	1		*TRIM PANEL -REAR SKIRT	Not Necessary	36.00 F	*- FL
9	1		*BUMPER -FACE REAR	Deformed	540.00 F	*540.00 FL
10	1		*BACK BEAM COMPLETE -REAR	Bent	288.00 F	*288.00 FL
11	1		*R BUMPER STEP RESIN	Necessary	420.00 F	*420.00 FL
12	1		*BRACKET -REAR BUMPER SIDE RIGHT	Not Necessary	14.40 F	*- FL
13	1		*BRACKET -REAR BUMPER SIDE LEFT	Not Necessary	14.40 F	*- FL
14	1		*BRACKET -REAR BUMPER CORNER ,RIGHT	Not Necessary	18.00 F	*- FL
15	1		*BRACKET -REAR BUMPER CORNER ,LEFT	Not Necessary	18.00 F	*- FL
16	1		*COVER -REAR BUMPER	Cut	12.60 F	*12.60 FL
17	1		*FLOOR PAN COMPLETE -REAR REAR	Repair	432.00 F	*- FL
18	1		*SKIRT COMPLETE -REAR	Repair	288.00 F	*- FL
19	1		*REFLEX REFLECTOR ASSEMBLY -RIGHT	Not Necessary	20.40 F	*- FL
20	1		*REFLEX REFLECTOR ASSEMBLY -LEFT	Not Necessary	20.40 F	*- FL
21	1		*LENS & BODY -REAR COMBINATION LAMP RIGHT	Not Necessary	432.00 F	*- FL
22	1		*LENS & BODY -REAR COMBINATION LAMP LEFT	Not Necessary	432.00 F	*- FL
23	1		*PROTECTOR -REAR GARNISH	Not Necessary	21.60 F	*- FL
24	2		*PROTECTOR -REAR GARNISH	Not Necessary	10.80 F	*- FL
25	1		*ORNAMENT	Not Necessary	79.20 F	*- FL
26	1		*LETTER MARK -REAR	Necessary	39.60 F	*39.60 FL
27	1		*LETTER MARK -REAR	Necessary	64.80 F	*64.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*HOLDER -JACK	Not Necessary	100.80 F	*- FL
29	1		*SPACER -SPARE TIRE	Not Necessary	37.50 F	*- FL
30	1		*COVER -TRUNK	Not Necessary	108.00 F	*- FL
31	1		*SPACER -REAR FLOOR SIDE RIGHT	Not Necessary	32.40 F	*- FL
32	1		*SPACER -REAR FLOOR SIDE LEFT	Not Necessary	32.40 F	*- FL
33	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,782.30	3,276.80
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	651.36
Total Parts (\$)	5,782.30	2,625.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR /REPLACE REAR BUMPER ,END PANEL ,BEAM ,TAILGATE & FLOOR PAN	New	3,920.00	2,240.00
2	RESPRAY REAR BUMPER ,END PANEL ,BEAM ,TAILGATE & FLOOR PAN	New	2,940.00	1,680.00
3	DISMANTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIR	New	900.00	0.00
4	REMOVE & REFIX EXHAUST	New	150.00	0.00
5	TRANSFER TAILGATE MECHANISM	New	150.00	150.00
6	WHEEL ALIGNMENT	New	200.00	0.00
7	REMOVE & REFIX CARPET ,SEATS TO REPAIRS	New	400.00	300.00
8	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	New	150.00	150.00
9	FAULT DIAGNOSTIC	New	280.00	0.00
10	TO REMOVE & REFIX FUEL TANK	New	200.00	0.00
11	TO CONDUCT REAR LIGHTING TEST	New	50.00	30.00
12	TO CONDUCT PROTECTANT COATING	New	500.00	0.00
13	TO CONDUCT ANTI RUST COATING	New	580.00	290.00
14	TO SUPPLY & INSTALL REVERSE SENSOR	New	300.00	0.00
15	TO SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	New	145.00	145.00
Gross Labour Cost (\$\$)			10,865.00	4,985.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >