

## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



o Reg No : 199405410K

**ESTIMATE** 

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Toh Hun Hoe Benjamin		
	Reg No/Reg Date	SFQ3361C / 31/07/201		
	Date In/Mileage	/ 0		
	Chassis No	KNACC81CVH5094024		
	Engine No	G4LEHS215680		
	Make/Model	KIA/NIRO 1.6 A		
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No			
LAX00000	Credit		QUD	247 / DonBong		28674			
		Description of Goods			Qty	<b>Unit Price</b>	Disc%	Ai	mount
		AMAGED PARST ON REAR	1			×		400	1200.00
REPAIR RI E PNT88000	EAR END I	PANEL							60.00
	ND INSTAL	L PARKING SENSOR						250	1050.00
E PNT98000 PAINT WOL	RK SPRAY	REAR END PANEL, REAF	t BUMPER	FACE				359	
AND AFFE									80.00
M SUNDRY APPLY BOX	OY SEALAN	NT							30.0
A 54900099					八八				30.0
CHECK WIF M SUNDRY	RING AND	CHASSIS ELECTRICAL C			111(0	7			80.0
TEIN OIL.	RUST PREV	ENTION L	S) (C			7			120.0
A 10028901	OUT DIAG	NOSTIC CHECK USING H	II-SCAN P	RO TEST					
USING HI-	-SCAN PRO	TEST							50.0
M SUNDRY	AD NUMBE	D DIATE WITH FRAME							
SUPPLY RE M SUNDRY	AK NUMBE	R PLATE WITH FRAME						20	50.0
SUNDRIES		NA	j		1.00	25.00	20.00		20.0
M BRACKET A	ASSY-RR E	SUMPER SIDE, LH 🗸 🗸	MM		1.00		20.00		20.0
M POACKET A	SCY-RR F	RUMPER SIDE, RH -	•		1.00		20.00		53.60
M STAY-RR E	BUMPER LH	1 20 600			1.00		20.00		53.60
M STAY-RR	BUMPER RE	1 - AND WILL			1.00	6.00	20.00		4.80
M BRACKET-	RR BEAM L	IPR MTG, LH ANX N	KI .		1.00	6.00	20.00		4.80
M BRACKET-	RR BEAM (	IND MTC DU			1.00		20.00		31.20
M ANTENNA	assy-smaf	RIKEY TO X AIN			1.00	261.00	20.00		208.80
M BEAM-RR	BUMPER	A WALL			1.00		20.00		4.80
M BRACKET-	RR RAIL I				1.00		20.00		4.80
M BRACKET-	RR BEAM I	WK, CIKA W LILI			1.00	5.00	20.00		4.00
M BRACKET-	SHAKI KE	1 1110			1.00	361.00	20.00		288.80
M WIRING H	AKNESS-RI	K BUMPEK - J. NOKI							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 2



## **CYCLE & CARRIAGE KIA PTE LTD** PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

## **ESTIMATE** GST Reg No : MR-8500111-X Owner Name & Vehicle Info Invoice Name & Address /Toh Hun Hoe Benjamin AIG Asia Pacific Insurance Pte. Cust No/Name / 31/07/201 Ltd. SFQ3361C Reg No/Reg Date MOTOR CLAIM DEPARTMENT Date In/Mileage 78 SHENTON WAY #09-16 KNACC81CVH5094024 Chassis No AIG BUILDING G4LEHS215680 Engine No SINGAPORE 079120 KIA/NIRO 1.6 A Make/Model Contact No 64191000 C3U DEEP CERULEAN B/ WK SATURN BLACK

Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	08/02/2021/ 10:45	QUD	247 / DonBong		28674		
LAXOCCOO	Credit	Description of Goods		\$	Qty	Unit Price		Amount
M REFLECTO	D/DEELEY	ASSY-RR RH 4 X N/	V	T	1.00	104.00		83.
M COVER-RR	RUMPER. L	IPR 1 X MM			1.00	486.00	20.00	388. 313.
M COVER-RR			a 1		1.00	392.00		12.
M PIECE-RR	BUMPER S	SIDE, RH / [M] (SI	(# )		1.00	135.00	20.00	108.
M SENSOR AS	SY-PARKI	ING ASSIST SYS 12 X	WM		1.00 1.00	135.00		108.
M SENSOR AS	SY-PARKI	NG ASSIST SYS X NA	ï		1.00	135.00		108.
M SENSOR AS	SY-PARKI	NG 433131 313			1.00	135.00		108.
M SENSOR AS M SKID PLAT	E-RR BUM	NO 433131 313			1.00	122.00		97.
			St	ima	9)	7		
		SURVEYOR N SURVEYOR S DATE : REMARKS : _	GNATURE	Steve CLKK):  WHL PHL  P/P  Ry ReL	8/2/21, 	10-30 an		
	LKK A	uto Consultants hence notile	The state of the s	3 day	15			
Confirm & acc	* Parts   * Third p	wive, Lefore/after sprny painting play damaged part(s) during resun prices are subject to confirmation party survey is on a "Without Prejuc gal modification(s) is allowed	•	74	GST on	Nett 4747.20		4,747.20 332.30
	<ul> <li>Supple</li> </ul>	ementary item(s) must be resurveyor ect to final approval from Insurance	ed <u>and</u> Company		Tota	l Payable		5,079.50
Authorized si	natory a	nd company stamp	•					

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.