



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 744Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAIL LAMP LH	CRACKED	256.00	256.00
2	REAR TAIL LAMP BRACKET (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR CHASSIS EXTENDER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-51.20	-51.20
			204.80	204.80
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE CAMERA WITH INFRA-RED (SN)	DENTED	398.00	398.00
1	NUMBER PLATE (SN)	DENTED	50.00	20.00
			448.00	418.00
<u>LABOUR</u>				
	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP BRACKET AND REAR CHASSIS EXTENDER.		800.00	350.00
	SPRAY PAINTING ON ACCIDENT AREAS.		800.00	200.00
	WIRING CHARGES.	NOT NECESSARY	150.00	-
	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS.	NOT NECESSARY	80.00	-
			1,830.00	550.00
GRAND TOTAL			2,482.80	1,172.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				900.00

Report Ref No. CS/AGI21001896/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.