

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3387P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
2	REAR BUMPER STAY LH/RH @\$138.10	NOT NECESSARY	276.20	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
2	REAR BUMPER REFLECTOR LH/RH @\$41.45	NOT NECESSARY	82.90	-
1	BOOTLID EMBLEM IONIQ	NOT NECESSARY	31.30	-
1	BOOTLID EMBLEM HYBRID	NOT NECESSARY	24.30	-
1	BUMPER FOG LAMP REAR	NOT NECESSARY	201.50	-
2	BUMPER LICENCE LAMP LH/RH @\$85.30	NOT NECESSARY	170.60	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	98.80	-
2	REAR BUMPER BRACKET RH/LH @\$55.80	NOT NECESSARY	111.60	-
	LESS 20% DISCOUNT		-464.93	-186.53
			1,859.72	746.12
	NETT ITEMS			
1	REAR NUMBER PLATE W/HOLDER (N)	CRACKED	55.00	55.00
1	COMFORTDELGRO LOGO/TEL STICKER (N)	NOT NECESSARY	60.00	-
1	REAR REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-29.50	-23.50
			265.50	211.50
	<u>LABOUR</u>			
	PANEL BEATING.		850.00	350.00
	SPRAY PAINTING CHARGE.		600.00	250.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			1,570.00	630.00
	GRAND TOTAL		3,695.22	1,587.62

Report Ref No. NS/INC21001904/T1qd3e2





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (CONFIRMED)

1,587.62

Report Ref No. NS/INC21001904/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser