



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7133L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER-FR BUMPER	DEFORMED	430.90	430.90
10	BUMPER COVER CLIP REAR	NECESSARY	22.00	22.00
1	LAMP ASSY-HEAD RH	NOT NECESSARY	1,993.65	-
1	LAMP ASSY-DAY RUNNING LIG	NOT NECESSARY	642.50	-
1	MOULDING-FRONT BUMPER RH	TO REPAIR SEE LABOUR	186.90	-
	LESS 20% DISCOUNT		-655.19	-90.58
			2,620.76	362.32
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF MOULDING-FRONT BUMPER RH.		400.00	350.00
	SPRAYPAINT ON AFFECTED AREA.		300.00	250.00
	CHECK AL LIGHTING.		50.00	30.00
			750.00	630.00
GRAND TOTAL			3,370.76	992.32
RECOMMENDED COST OF REPAIRS (CONFIRMED)				992.32

Report Ref No. NS/INC21001914/T1td3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.