

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315 Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2805G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR LH DOOR PANEL	TO REPAIR SEE LABOUR	1,789.90	-
1	LH ROCKER OUTER GARNISH	TO REPAIR SEE LABOUR	715.00	-
1	REAR DOOR OUTER MOULDING LH	TO REPAIR SEE LABOUR	166.20	-
1	WHEEL CAP LH	CUT	346.40	346.40
	LESS 20% DISCOUNT		-603.50	-69.28
			2,414.00	277.12
	NETT ITEMS			
1	REAR DOOR COMFORT APP (N)	CUT	80.00	80.00
	LESS 10% DISCOUNT		-8.00	-8.00
			72.00	72.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR LH DOOR PANEL,LH ROCKER OUTER GARNISH AND REAR DOOR OUTER MOULDING LH.		650.00	525.00
	SPRAY PAINTING CHARGE.		700.00	625.00
	REMOVE/REFIX DOOR PARTS.	NOT NECESSARY	90.00	-
	CHECK WIRING.		50.00	30.00
			1,490.00	1,180.00
	GRAND TOTAL		3,976.00	1,529.12
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			1,529.12

Report Ref No. NS/INC21001915/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.