

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

21-7044

Date:

23/12/2020

INVOICE NO.

7044

7

Foodgnostic Pte Ltd

c/o Triple-T Automobile Blk 6 Defu Lane 10 #01- 556 Singapore 539187

Registration No.

YP6525H

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

| | , process, process, and process and an arrange of the process of t | Total amount | \$ 1,424.00 |
|-------|--|--------------|-------------|
| 1 | Being vehicle damage assessment report, inspection, photográphs, transport and miscellaneous. | 1 | \$ 1,424.00 |
| S/No. | Description of Services Provided | Qty | Amount |

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

7

L.L.Tan (Ms)

Principal Consultant

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd Infoknights International Services (Philippines) IABN Pte Ltd

 www.iaconsultingsg.com



Our reference:

21-7044

Date:

23/12/2020

c/o Triple-T Automobile Blk 6 Defu Lane 10 #01- 556 Singapore 539187

Dear Sirs

RE:

Road Traffic Accident on 26/9/2020

Foodgnostic Pte Ltd

In accordance with your instructions received in this office or 2/11/2020 , we made arrangements to examine the vehicle on 2/11/2020 at above-mentioned address. The following data was

recorded:

Vehicle details

| Make | Misubishi | Registration | YP6525H |
|-----------|--------------------|--------------|--------------|
| Model | Canter FEB21CR3SDE | Chassis | FEB21CA20053 |
| Colour | White | Gearbox | Auto |
| Odometer | 139279km | Paintwork | Good |
| Steering | Good | Brakes | Good |
| Condition | Good | | |

Tyre Depths


| Front left | • | • |
|-------------|---|---|
| Front right | • | • |
| Rear left | * | • |
| Rear right | • | • |

| Status | REPAIRABLE | | |
|--------------|--------------|--|--|
| Magnitude | Medium | | |
| Legal status | Unroadworthy | | |

Impact Direction & Area of Damage:

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$51,400.00 and 30 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
 Infoknights International Services (Philippines)
 IABN Pte Ltd
 www.iaconsultingsg.com



Our reference

21-7044

Date

23/12/2020

Page

2

Section A: Damaged Parts Assessment

| Part's Description | Qty | Condition As inspected | Repairer's Estimate | Our |
|------------------------------------|-----|---------------------------|------------------------|------------|
| List Items: | | mspected | Limate | Adjustment |
| Front bumper | 1 | damaged | 961.54 | 961.54 |
| Front bumper side @\$285.50 | 2 | damaged | 571.00 | 571.00 |
| Front bumper bracket @\$175.80 | 2 | damaged | 351.60 | 351.60 |
| Frot bumper cross member | 1 | damaged | 721.50 | 721.50 |
| Head lamp @\$652.30 | 2 | damaged | 1304.60 | 1304.60 |
| Side lamp @\$223.47 | 2 | damaged | 446.94 | 446.94 |
| Head lamp lower lamp @\$412.00 | 2 | damaged | 824.00 | 824.00 |
| Radiator grille | 1 | damaged | 618.23 | 618.23 |
| Radiator grille logo | 1 | necessary | 42.50 | 42.50 |
| Radiator grille emblem 'canter" | 1 | necessary | 85.00 | 85.00 |
| Front panel | 1 | damaged | 1015.46 | 1015.46 |
| Front panel emblem 'FUSO' | 1 | necessary | 64.25 | 64.25 |
| Front wiper garnish (white) | 1 | damaged | 425.00 | 425.00 |
| Front windscreen rubber | 1 | necessary | 475.21 | 475.21 |
| Front corner panel Ih | 1 | damaged | 307.09 | 307.09 |
| Front windscreen glass | 1 | damaged | 1658.70 | 1658.70 |
| Front side mirror assy Ih | 1 | damaged | 689.80 | 689.80 |
| Front door @\$1754.50 | 2 | damaged | 3509.00 | 3509.00 |
| Front door weatehrstrip @\$233.00 | 2 | damaged | 466.00 | 466.00 |
| Front door inner lock @\$298.75 | 2 | damaged | 597.50 | 597.50 |
| Front door hinge @\$98.00 lh | 2 | damaged | 196.00 | 196.00 |
| Front door inner board @\$411.00 | 1 | damaged | 822.00 | 822.00 |
| Front door lower garnish Ih | 1 | damaged | 144.00 | 144.00 |
| Front door garnish inner rubber Ih | 1 | damaged | 85.00 | 85.00 |
| Front door check pin @\$125.00 | 2 | damaged | 250.00 | 250.00 |
| Front door air vent lh | 1 | damaged | 102.00 | 102.00 |
| | | | | 102.00 |

Subsidiaries of Impact Analysis Consultant:

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd

[●] IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd www.iaconsultingsg.com



Our reference

21-7044

Date

23/12/2020

| Front door window moulding @\$165.00 | 2 | necessary | 330.00 | 330.00 |
|--|-----|-----------|---------|---------|
| Front door window lower moulding @\$144.00 | 2 | necessary | 288.00 | 288.00 |
| Front door step garnish lh | 1 | damaged | 188.50 | 188.50 |
| Front door step garnish panel Ih | 1 | damaged | 344.00 | 344.00 |
| Front door step garnish panel bracket Ih | 1 | damaged | 231.00 | 231.00 |
| Front windscreeen pillar 'A' lh | 1 | damaged | 418.52 | 418.52 |
| Front passenger floor panel | 1 | damaged | 681.10 | 681.10 |
| Aircon condenser | 1, | damaged | 1458.90 | 1458.90 |
| Aircon pipes | set | damaged | 720.00 | 720.00 |
| Aircon condenser bracket | set | damaged | 125.00 | 125.00 |
| Aircon duct | 1 | damaged | 341.00 | 341.00 |
| Aircon casing | 1 | damaged | 147.50 | 147.50 |
| Aircon blower assy | 1 | damaged | 741.00 | 741.00 |
| Aircon dryer | 1 | damaged | 244.00 | 244.00 |
| Aircon cooling coil | 1 | damaged | 598.80 | 598.80 |
| Radiator fan cowling | 1 | damaged | 296.78 | 296.78 |
| Dashboard | 1 | damaged | 854.10 | 854.10 |
| Dashboard underneath cover | 1 | damaged | 178.00 | 178.00 |
| Dashboard reinforcement | 1 | damaged | 345.89 | 345.89 |
| Dashboard bracket | 1 | damaged | 185.40 | 185.40 |
| Wiper tank | 1 | damaged | 175.00 | 175.00 |
| Wiper tank motor | 1 | damaged | 142.00 | 142.00 |
| Fuse box | 1 | damaged | 485.00 | 485.00 |
| Fuse box wiring | 1 | damaged | 250.00 | 250.00 |
| Fuse box bracket | 1 | damaged | 110.00 | 110.00 |
| Radiator spare tank | 1 | damaged | 233.50 | 233.50 |
| Radiator spare tank bracket frame | 1 | damaged | 214.80 | 214.80 |
| Power steering tank | 1 | damaged | 189.00 | 189.00 |
| Brake fill oil tank | 1 | damaged | 175.80 | 175.80 |
| Front cabin (rear panel) | 1 | damaged | 754.80 | 754.80 |
| Front cabin (rear fender) lh | 1 | damaged | 589.00 | 589.00 |
| | | | | |

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Subsidiaries of Impact Analysis Consultant:

 [■] Impact Analysis Consulting Pte Ltd
 ■ Impact Analysis Academy Pte Ltd
 ■ IA Racking Solutions Pte Ltd

 [■] IA Accounting & Consultancy Pte Ltd
 ■ Infoknights International Services (Philippines)
 ■ IABN Pte Ltd www.iaconsultingsg.com



Our reference

21-7044

| our reference | 21-7044 | | | | |
|----------------------------|-------------------------------|---------|-------------|----------|----------|
| Date | 23/12/2020 | | | | |
| Front cabin lever | | 1 | damaged | 385.90 | 385.90 |
| Front cabin mountin | g @\$350.00 | 2 | damaged | 700.00 | 700.00 |
| Driver seat | | 1 | twisted | 854.00 | 854.00 |
| Driver seat mounting | g bracket | 1 | damaged | 150.00 | 150.00 |
| Front steering colum | ın | 1 | damaged | 466.00 | 466.00 |
| Front cabin inner lin | ing | 1 | damaged | 591.00 | 591.00 |
| Front cabin roof top | panel | 1 | repair | 1542.00 | 0.00 |
| Front wheel arc pane | el lh | 1 | damaged | 398.78 | 398.78 |
| Front weel arc garns | h lh | 1 | damaged | 168.80 | 168.80 |
| | Sub- | Total | costs | 34026.79 | 32484.79 |
| | Percentage disco | ount: | 10% | 3402.68 | 3248.48 |
| | Sub-Tota | l costs | s for parts | 30624.11 | 29236.31 |
| | | | | | |
| Special Nett Items: | | | | | |
| Freezer box: | | | | | |
| Side panel lh | | 1 | damaged | 5620.00 | 5620.00 |
| Side door Ih | | 1 | damaged | 2600.00 | 2600.00 |
| Side door gasket Ih | | 1 | damaged | 460.00 | 460.00 |
| Corner guard CD117 | 45x6100mm lh @\$350.00 | 3 | damaged | 1050.00 | 1050.00 |
| Corner bitting CD11 | 746x6100mm lh @\$125.00 | 6 | damaged | 750.00 | 750.00 |
| Fibreglass end cap n | nodel 97 lh | 2 | damaged | 165.00 | 165.00 |
| Side door external h | andle E22mm/2010 lh | 1 | damaged | 412.00 | 412.00 |
| Locking bar with car | n lock lh | 1 | damaged | 653.00 | 653.00 |
| Sealant @\$80.00 | | 4 | necessary | 320.00 | 320.00 |
| Side door frame Ih | | 1 | damaged | 812.50 | 812.50 |
| Labour charge for free | ezer box repair/installlation | ٠ | • | • | • |
| • see labour calculation | on | | | | |
| Front number plate | | 1 | damaged | 50.00 | 50.00 |
| Brake oil | | 1 | necessary | 150.00 | 150.00 |
| Power steering oil | | 1 | necessary | 150.00 | 150.00 |
| | | | | | |

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Subsidiaries of Impact Analysis Consultant:

Front windscreen sealant

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd

necessary

80.00

13272.50

80.00

13272.50

1

Sub-Total costs for parts

■ IA Accounting & Consultancy Pte Ltd
 ■ Infoknights International Services (Philippines)
 ■ IABN Pte Ltd www.iaconsultingsg.com



Our reference

21-7044

Date

23/12/2020

Parts Repair

* * 0.00 0.00

Sub- Total costs 0.00 0.00

Total costs for parts 43896.61 42508.81

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171



Our reference

21-7044

Date

23/12/2020

Page

3

Section B: Labour Cost Calculation

| | Hourly rate | Manhr, Req. | | Total |
|---|-------------|----------------|-----|----------|
| To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts (exclude installation / repair of freezer box) | * | • | \$ | 3,900.00 |
| Freezer Box: To supply labour, material and equipment to replace whole side panel (left) & side door (left), replace side door handle & locking bar, replace alumimium corner guard with bitting, reconseal interior and exterior of box with sikaflex, assemble door panel an realignment, final touch up and cleaning | | | \$ | 4,100.00 |
| Putty & Spray painting to adjacent panels. Job allowance. Paint / material. | Sub-con | tract work. | \$ | 1,800.00 |
| Apply rust proofing on the adjacent panels. | Sub-con | tract work. | \$ | 350.00 |
| Remove / replace front windscreen glass (2-man job) | • | * | \$ | 200.00 |
| Remove / replace aircon condenser and refill aircon gas | * | • | \$ | 150.00 |
| Remove / refix radiator, top up coolant & conduct pressure test | | • | \$ | 100.00 |
| Remove and refix front cabin to facilitate the replacement of cabin mounting. (inclusive of lifting-tools) | •, | • | \$ | 800.00 |
| To remove and replace dashboard and internal wiring | : * | ** | \$ | 280.00 |
| Outsource contractor - Towing charges (king rolley) (two trips) | - | - | \$ | 240.00 |
| Transfer of existing front door mechanism to new door (2 nos) | * | • | \$ | 200.00 |
| Remove and refix upholstery to facilitate the repair works | * | • | \$ | 300.00 |
| Specialist charges - Conduct front chassis alignment | | r - | \$ | 550.00 |
| Wiring / control wiring / bulb checking / commissioning. | • | • | \$ | 200.00 |
| | Total la | bour cost | \$1 | 3,170.00 |

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
 Infoknights International Services (Philippines)
 IABN Pte Ltd www.iaconsultingsg.com

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171



#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

No.25 Kaki Bukit Road 4

Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore

Our reference

21-7044

Date

23/12/2020

Section C: Summary Table of Total Repair Cost

| Description Damaged Parts Assessment (See section A) | | Cost | |
|--|----------------|-------------|-----------|
| | | \$42,508.81 | |
| Further discount 10% | | \$4,250.88 | |
| Recommended cost of parts | | \$38,257.93 | (1) |
| | et Calculation | \$13,170.00 | (2) |
| Total Repair Cost (Round off to hundred) | | \$51,400.00 | (1) + (2) |

| We would recommend a sum of _ | \$51,400.00 | and | 30 | working days for repair. |
|------------------------------------|------------------|--------------------|----------------|--------------------------|
| No further items will be approved | without our expr | essed written agre | ement. Any sig | nificant additional |
| items will be subject to a supplem | entary report. | | | |

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diplomd Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

Enterprise Singapore - Recognised Certification for Management Consultants

IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
 Infoknights International Services (Philippines)
 IABN Pte Ltd www.iaconsultingsg.com

