

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 1826E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED	878.60	353.10
1	REAR BUMPER SIDE BRACKET RH	SERVICEABLE	118.40	-
1	REAR BUMPER TOWING COVER	DENTED	36.70	36.70
1	REAR BUMPER GARNISH COVER RH	MTG CRACKED	89.30	89.30
1	REAR BUMPER REINFORCEMENT	BENT	322.00	322.00
1	REAR BUMPER LOWER LIP COVER	DENTED	366.70	366.70
1	REAR END PANEL UPPER COVERING	SERVICEABLE	250.00	-
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR TAILGATE (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-515.43	-291.95
			1,546.27	875.85
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	300.00	200.00
1	REAR END PANEL UPPER COVERING CLIPS (SN)	NOT NECESSARY	30.00	-
			380.00	250.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST REAR ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR TAILGATE.		700.00	400.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER,REAR END PANEL,REAR TAILGATE & ETC.		700.00	320.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.		100.00	50.00
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		80.00	15.00
			1,580.00	785.00
	GRAND TOTAL		3,506.27	1,910.85

Report Ref No. CS/AGI21001925/Kqf3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI21001925/Kqf3q2

KONG SENG CHEONG

Licensed Appraiser