

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001926/T1TD3Q2**Date:** 19/03/2021**REFERENCE**

Insured/Claimant: BERENICE G LOW Policy No: 1800149035
Date of Loss: 05/02/2021 Nature of Claim: OD Claim No: 9110719850SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG3041X**
Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UHK0848
Reg. Date: 14/12/2018 (Man. Year: 2018) Chassis No: MMBSTA13AJH004410
Colour: Silver Odometer: 22179 km
Engine Capacity: 1193 cc
Market Value/New Car Price: S\$55,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,328.20	1,867.19	461.01	19.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,570.00	3,400.00	1,170.00	25.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,898.20	5,267.19	1,631.01	23.64
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	6,298.20	4,667.19	1,631.01	25.90
+ GST 7.00/7.00% (S\$)	440.87	326.70	114.17	25.90
Nett Amount (S\$)	6,739.07	4,993.89	1,745.18	25.90

INSPECTION

Date of Assignment: 09/02/2021

Date Inspected: 17/02/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY,COMB,RR LH	Cut	337.00 FL	*337.00 FL
2	1		*LAMP ASSY,COMB,RR RH	Cracked	337.00 FL	*337.00 FL
3	1		*REFLECTOR RH	Not Necessary	23.00 FL	*- FL
4	1		*FACE,RR BUMPER	Deformed	751.00 FL	*751.00 FL
5	4		*CLIP,RR BUMPER	Not Necessary	16.00 FL	*- FL
6	1		*BRACKET,RR BUMPER,LH	Not Necessary	28.00 FL	*- FL
7	1		*BRACKET,RR BUMPER,RH	Not Necessary	28.00 FL	*- FL
8	1		*PANEL,TRUNK LID	Bent	795.00 FL	*795.00 FL
9	1		*LATCH,TRUNK LID	Not Necessary	218.00 FL	*- FL
10	1		*MARK,THREE-DIA	Necessary	70.00 FL	*70.00 FL
11	1		*MARK,ATTRAGE	Necessary	21.00 FL	*21.00 FL
12	1		*DECAL,MIVEC	Necessary	36.00 FL	*36.00 FL
13	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
14	1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS
15	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,940.00	2,407.00
- List Item Discount on L Items 23.00/23.00% (\$)	611.80	539.81
Total Parts (\$)	2,328.20	1,867.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER & BOOTLID.REPAIR/ALIGN RR END PNL,LHR FENDER & RHR FENDER	New	1,800.00	1,350.00
2	RESPRAY RR BUMPER,BOOTLID,RR END PNL,LHR FENDER & RHR FENDER	New	1,750.00	1,050.00
3	REMOVE & REFIT BOOTLID COMPONENT	New	120.00	120.00
4	REMOVE & REFIT TT FLR BOARD,TRIM & CARPET	New	120.00	120.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	REMOVE & REFIT REVERSE SENSOR	New	80.00	60.00
8	REPAIR RH REAR FENDER SUPPLEMENTARY	New	200.00	200.00
9	SPRAY PAINT RH REAR FENDER SUPPLEMENTARY	New	350.00	350.00
Gross Labour Cost (\$\$)			4,570.00	3,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >