5/17/2021 Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001927/QTD3E2

Date: 17/05/2021

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00135322000

TP

**Claimant Vehicle** 

SMD8063R

Insured Vehicle No:

SJM1981A

No: Date of Loss: 30/01/2021

Nature of

Claim:

Claim SNM21D200757/C02/THAMYL

WVWZZZAUZFW015241

CXS213274

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SMD8063R Reg No:

Make & Model: VOLKSWAGEN GOLF A7, 1.4 (A)

Reg. Date: 08/09/2014 (Man. Year: 2014) Chassis No:

> Odometer: 71493 km

Engine No:

Colour: Red

**Engine Capacity:** 1395 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Excellent Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

**CONDITION OF TYRES** 

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18 Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,558.00	6,208.00	5,350.00	46.29
Miscellaneous Items	1,680.00	1,560.00	120.00	7.14
Labour	1,562.40	1,037.40	525.00	33.60
Paintwork Labour	821.58	834.32	-12.74	-1.55
Towing	0.00	0.00	0.00	
Calculated Gross Total (S	15,621.98	9,639.72	5,982.26	38.29
Approved Total (Overridden) (S	5\$)	7,700.00		
(\$	15,621.98	7,700.00	7,921.98	50.71
+ GST 7.00/7.00% (S	<b>5\$)</b> 1,093.54	539.00	554.54	50.71
Nett Amount (S	16,715.52	8,239.00	8,476.52	50.71

**INSPECTION** 

Date of Assignment: 09/02/2021 Auto Insure Pte Ltd (HQ) (Woodlands) Present Location:

Auto Insure Pte Ltd (HQ) (Woodlands)

09/02/2021 6 Marsiling Lane Date Inspected: Inspected At:

Singapore 739145

Estimated Period of Repair: 9.0 days

Adjuster: OI SUN PIN Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### REPAIR DETAILS

### Reference

5/17/2021

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 May 2021)

Parts: 143 VOLKSWAGEN GOLF A7 1.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMD8063R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		8,285.00 F	*2,490.00 F
2	1		*R/F OUT BUMPER BRKT	Broken	-	*15.00 F
3	1		*R/F S-ABSORB BRACKET	Broken	-	*80.00 F
4	1		*R/WHEEL BEARING HSG	Bent	-	*350.00 F
<u>Sup</u>	<u>pleme</u>	entary #1				
5	1		*R/S/ABSORBER BUFFER	Necessary	25.00 F	*25.00 F
6	1		*R/F DAMPER PROTECT	Necessary	22.00 F	*22.00 F
7	1		*ENGINE PROTECTION	Crumpled	120.00 F	*120.00 F
8	1		*RELAY HORN	Shorted	6.00 F	*6.00 F
9	1		*R/DRIVE SHAFT CPL	Bent	1,450.00 F	*1,450.00 F
10	1		*POWER STEERING	Cracked	1,150.00 F	*1,150.00 F
11	1		*STEERING ANGLE SENSOR	Necessary	500.00 F	*500.00 F
F=Fra	nchise	part.				
				Total Parts (S\$)	11,558.00	6,208.00
Report was unsubmitted during this print-out.						

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellar	neous Items			
1	1	EXTRAS		1,430.00	1,310.00
<u>Sup</u>	Supplementary #1				
2	1	REAR WHEEL TYRE RH (BROKEN)		250.00	250.00
			Sub Total (S\$)	1,680.00	1,560.00

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Pair</u>	ntwork Labour			
1	LABOUR FOR SPRAY PAINTING	New	821.58	834.32
<u>Lab</u>	our Items			
2	LABOUR FOR PANEL BEATING	New	1,562.40	1,037.40
		Gross Labour Cost (S\$)	2,383.98	1,871.72

Report was unsubmitted during this print-out.

< END OF ESTIMATES >