

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001933/EVF3Q2

Date: 19/03/2021

REFERENCE

Insured/Claimant:	TAN BOON SOO	Policy No:	1800145347		
Date of Loss:	09/02/2021	Nature of Claim:	OD	Claim No:	0984989301SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFT7710L		Engine No:	G4FGJH712643
Make & Model:	KIA CERATO, 1.6 (A)		Chassis No:	KNAF3416MK5022966
Reg. Date:	07/12/2018 (Man. Year: 2018)		Odometer:	25881 km
Colour:	Blue			
Engine Capacity:	1591 cc			
Market Value/New Car Price:	S\$66,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,899.00	3,261.60	2,637.40	44.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,180.00	5,420.00	760.00	12.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,079.00	8,681.60	3,397.40	28.13
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	11,779.00	8,381.60	3,397.40	28.84
+ GST 7.00/7.00% (S\$)	824.53	586.71	237.82	28.84
Nett Amount (S\$)	12,603.53	8,968.31	3,635.22	28.84

INSPECTION

Date of Assignment:	09/02/2021	
Date Inspected:	09/02/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	9.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL-FENDER LH	Dented	430.00 F	*430.00 FL
2	1		*INSULATOR-FENDER LH	Crushed	27.00 F	*27.00 FL
3	1		*MIRROR ASSY-OUTSIDE RR VIEW,LH	Cut	559.00 F	*559.00 FL
4	1		*PANEL ASSY-FRONT DOOR,LH	Dented	1,277.00 F	*1,277.00 FL
5	1		*HINGE ASSY-FRONT DOOR,LH	Not Necessary	30.00 F	*- FL
6	1		*HINGE ASSY-DOOR LOWER,LH	Not Necessary	27.00 F	*- FL
7	1		*MOULDING ASSY-FRT DR FRAME,LH	Necessary	37.00 F	*37.00 FL
8	1		*W/STRIP ASSY-FR DR BELT O/S LH	Not Necessary	64.00 F	*- FL
9	1		*W/STRIP ASSY-FR DR SIDE LH	Not Necessary	102.00 F	*- FL
10	1		*HANDLE ASSY-DOOR OUTSIDE,LH	Broken	164.00 F	*164.00 FL
11	1		*PAD-FR DR O/S HDL HINGE,LH	Missing	5.00 F	*5.00 FL
12	1		*COVER-FR DR O/S HDL LH	Missing	14.00 F	*14.00 FL
13	1		*PAD-FR DR O/S HDL COVER,LH	Missing	5.00 F	*5.00 FL
14	1		*BASE ASSY-FR DR O/S HANDLE LH	Broken	52.00 F	*52.00 FL
15	1		*CHECKER ASSY-FRONT DOOR,LH	Not Necessary	44.00 F	*- FL
16	1		*LATCH ASSY-FRONT DOOR,LH	Not Necessary	400.00 F	*- FL
17	1		*GLASS ASSY-FRONT DOOR,LH	Not Necessary	207.00 F	*- FL
18	1		*PANEL ASSY-FRONT DR MODULE,LH	Not Necessary	241.00 F	*- FL
19	1		*PANEL ASSY-REAR DOOR,LH	Dented	1,377.00 F	*1,377.00 FL
20	1		*GUARD ASSY-FRONT WHEEL,LH	Not Necessary	95.00 F	*- FL
21	1		*HUB ASSY-FR WHEEL	Not Necessary	436.00 F	*- FL
22	1		*BLACK TAPE-FR DR RR,LH	Necessary	13.00 F	*13.00 FL
23	1		*BLACK TAPE-RR DR FR,LH	Necessary	13.00 F	*13.00 FL
24	1		*BLACK TAPE-RR DR FRAME RR OTR	Necessary	8.00 F	*8.00 FL
25	1		*GLASS ASSY-REAR DOOR,LH	Not Necessary	181.00 F	*- FL
26	1		*MOULDING ASSY-RR DR FRAME,LH	Necessary	44.00 F	*44.00 FL
27	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
28	1		*FILM-ANTI CHIPPG LH (Supplementary)	Necessary	27.00 F	*27.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,899.00	4,072.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	810.40
Total Parts (S\$)	5,899.00	3,261.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT FENDER LH,FRT DOOR LH,REAR DOOR LH,WINDMIRROR LH,REPAIR SIDE SILL LH,REAR FENDER LH,REAR BUMPER	New	2,000.00	1,600.00
2	REMOVE & INSTALL FRT DOOR TRIMS AND GLASS	New	150.00	120.00
3	REMOVE & INSTALL REAR DOOR TRIMS AND GLASS	New	150.00	120.00
4	SPRAY PAINT FOR FRT FENDER LH,FRT DOOR LH,REAR DOOR LH,SIDE SILL LH,REAR FENDER LH,REAR BUMPER,WINDMIRROR LH	New	2,450.00	2,450.00
5	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
6	TRANSFER FRT LEFT AND REAR LEFT RIM	New	60.00	60.00
7	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	80.00
8	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
10	RENEW FRT UNDER CARRIAGE	New	300.00	0.00
11	SUPPLY FRT RIM LEFT	New	360.00	360.00
12	SUPPLY REAR RIM LEFT	New	360.00	360.00
Gross Labour Cost (\$\$)			6,180.00	5,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >