

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC6/AIG21001936/T1PA3Q2  
**Date:** 10/01/2022

**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100450598   |
| <b>Claimant Vehicle No :</b> | GBB1685H                             | <b>Insured Vehicle No :</b> | SKZ6596R     |
| Date of Loss:                | 22/01/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 9330905178SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                           |             |                   |
|-----------------------------|-------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>GBB1685H</b>                           | Engine No:  | 1KD1835520        |
| Make & Model:               | TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M) | Chassis No: | JTFAT35Y103001904 |
| Reg. Date:                  | 21/08/2008 (Man. Year: 2008)              | Odometer:   | 442469 km         |
| Colour:                     | Blue                                      |             |                   |
| Engine Capacity:            | 2982 cc                                   |             |                   |
| Market Value/New Car Price: | N/A                                       |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>         |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |              |                  |                |
|-------------------|--------------|------------------|----------------|
| Front Tyre Size:  | 195 R15      | Rear Tyre Size:  | 155 R12 (D)    |
| Front Left Side:  | Hankook 6 mm | Rear Left Side:  | Hankook 6/6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6/6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 0.00              | 0.00              | 0.00              |               |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 450.00            | 350.00            | 100.00            | 22.22         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>450.00</b>     | <b>350.00</b>     | <b>100.00</b>     | <b>22.22</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>31.50</b>      | <b>24.50</b>      | <b>7.00</b>       | <b>22.22</b>  |

|                                                  |               |               |               |              |
|--------------------------------------------------|---------------|---------------|---------------|--------------|
| <b>Nett Amount (S\$)</b>                         | <b>481.50</b> | <b>374.50</b> | <b>107.00</b> | <b>22.22</b> |
| <b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b> |               | 300.00        |               |              |
| <b>(S\$)</b>                                     |               | 674.50        |               |              |
| <b>Liable Amount (50.00%) (S\$)</b>              |               | <b>337.25</b> |               |              |
| <b>+ Doc/Search Fee (S\$)</b>                    |               | 2.00          |               |              |
| <b>Nett Liability (S\$)</b>                      |               | <b>339.25</b> |               |              |
| <b>Global Sum Settlement (S\$)</b>               |               | <b>300.00</b> |               |              |

INSPECTION

Date of Assignment: 09/02/2021

Date Inspected: 09/02/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Tan Lim Motor Pte Ltd (Defu)  
1 Defu Lane 6  
Singapore 539365

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                          | Lab.Type | Repairer's    | Amount        |
|---------------------------------|----------------------------------------------------------------------------------------------------------------------|----------|---------------|---------------|
| <u>Labour Items</u>             |                                                                                                                      |          |               |               |
| 1                               | PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION REMOVE AND RENEWAL OF PARTS ADJUST AND REALIGN THE SAME | New      | 200.00        | 200.00        |
| 2                               | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION                                                                     | New      | 250.00        | 150.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                      |          | <b>450.00</b> | <b>350.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >