

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
 AIG Building, 78 Shenton Way #07-16
 Singapore 079120

Our File No: CS/AIG21001937/ETD3Q2
Date: 19/03/2021

REFERENCE

Insured/Claimant:	SONG HAIMING	Policy No:	2070119441		
Date of Loss:	09/02/2021	Nature of Claim:	OD	Claim No:	6154570550SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU5621K		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11CL0581
Reg. Date:	19/08/2020 (Man. Year: 2020)	Chassis No:	GF7W0700517
Colour:	White	Odometer:	3993 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$110,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,016.53	4,740.10	276.43	5.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,025.00	1,675.00	1,350.00	44.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,041.53	6,415.10	1,626.43	20.23
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	7,441.53	5,815.10	1,626.43	21.86
+ GST 7.00/7.00% (S\$)	520.91	407.06	113.85	21.86
Nett Amount (S\$)	7,962.44	6,222.16	1,740.28	21.86

INSPECTION

Date of Assignment:	09/02/2021	
Date Inspected:	09/02/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

3/19/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MOULDING,FR BUMPER,LH	Missing	97.00 FL	*97.00 FL
2	1		*MOULDING,FR WHEEL ARCH,LH	Cut	168.00 FL	*168.00 FL
3	1		*SHIELD,FR WHEELHOUSE,LH	Missing	164.00 FL	*164.00 FL
4	1		*FACE,FR BUMPER	Broken	863.00 FL	*863.00 FL
5	1		*BRACKET,FR BUMPER SIDE,LH	Broken	18.00 FL	*18.00 FL
6	1		*GARNISH,FR BUMPER,LH	Missing	48.00 FL	*48.00 FL
7	1		*GARNISH,FR BUMPER SIDE	Missing	48.00 FL	*48.00 FL
8	1		*GARNISH,FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
9	1		*GARNISH,FR BUMPER SIDE	Broken	112.00 FL	*112.00 FL
10	1		*COVER,FR BUMPER	Not Necessary	359.00 FL	*- FL
11	1		*EXTENSION,FR BUMPER	Broken	517.00 FL	*517.00 FL
12	1		*HEADLAMP ASSY,LH	Broken	1,948.00 FL	*1,948.00 FL
13	1		*LAMP ASSY,FOG,FR LH	Broken	350.00 FL	*350.00 FL
14	1		*RIM LH FRT NPA	Cut	0.00 FL	*- FL
15	1		*ENGINE SIDE COVER,LH NPA	Broken	0.00 FL	*- FL
16	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
17	1		*CLIP, RR BUMPER (10PCS) Supplementary	Necessary	30.00 FL	*30.00 FL
18	1		*BRKT, FR BUMPER SIDE, LWR LH Supplementary	Broken	6.00 FL	*6.00 FL
19	1		*ARM ASSY, FR SUSP, LWR LH Supplementary	Bent	325.00 FL	*325.00 FL
20	1		*WHEEL, DISC Supplementary	Cut	974.00 FL	*974.00 FL
21	1		*COVER, ENG ROOM. UNDER , FR Supplementary	Broken	150.00 FL	*150.00 FL
22	1		*COVER, ENG ROOM. SIDE, LH Supplementary	Broken	92.00 FL	*92.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,509.00	6,150.00
- List Item Discount on L Items 23.00/23.00% (S\$)	1,492.47	1,409.90
Total Parts (S\$)	5,016.53	4,740.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER,REPAIR/ALIGN LHF FENDER	New	1,800.00	450.00
2	RESPRAY FRT BUMPER & LHF FENDER	New	700.00	700.00
3	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	R&R RIM NPA	New	0.00	0.00
6	ALIGNMENT NPA	New	0.00	0.00
7	RENEW LH FRONT LOWER ARM & ENGINE UNDER COVER Supplementary	New	225.00	225.00
8	SUPPLY LABOUR FPR INSTALLATION LH FRONT RIM Supplementary	New	30.00	30.00
9	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
Gross Labour Cost (\$\$)			3,025.00	1,675.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >