

ASS. REC. BY:

Tang Jkh

REF:

CC4/MIG 21001943/Ti 693

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$76K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SRL88H

Yr Regn:

219,00t

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Cerato 1.6

c.c

1591

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

45711

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAF3416ME5054644

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

1 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

9/2/21

Survey held at

Tan Lim.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Rep. Format:

Lump Sum / L.B. / C



陳林摩摩私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SKP7624P

Date of Accident : 08 February 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Tan Peng Hong

Date : 08 February 2021

Lek - Taufik

Estimate To Repair SBC88H - KIA Cerato 1.6A

Chassis No : KNAF3416ML5054644

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper	\$ 575.00 Rx
02	8 ps	front bumper clips @ \$4.50	\$ 36.00 X
03	1 pc	front bumper centre grille	\$ 155.00 X
04	1 pc	front bumper fog lamp n/s	\$ 140.00 X
05	1 pc	front bumper day light n/s	\$ 185.00 ?
06	1 pc	front bumper daylight inch n/s	\$ 65.00 ent-
07	1 pc	front bumper side retainer n/s	\$ 18.00 ?
08	1 pc	headlamp n/s	\$ 686.00 X
09	1 pc	n/s front wheel bearing	\$ 108.00 ?
		Less 20 %	\$ 1,968.00
			\$ 393.60
			\$ 1,574.40
		<u>SPECIAL NETT ITEMS</u>	
10	1 pc	n/s front spot rim	\$ 450.00 ent-
			\$ 450.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of tyre, rim and on wheel balancing.	\$ 60.00 30.
02		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 180.00 100? photo.
03		To check steering geometry and computer wheel alignment.	\$ 120.00 80
04		To check electrical lighting concerned.	\$ 120.00 30.
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00 200
06		Putty and spray painting of the affected portion.	\$ 400.00 200
			\$ 1,380.00
		Total	\$ 3,404.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495499 / 62563561

WP' 9/2/21 @ 1045

3 days

Resurvey new parts

taufik@lkkauto.com