

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21001944/GQD3N2**Date:** 11/11/2021REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MPC20P00052600
Claimant Vehicle No :	SJY1147D	Insured Vehicle No :	SJL199D
Date of Loss:	04/02/2021	Nature of Claim:	TP
		Claim No:	DMPC2100044H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY1147D	Engine No:	27186030069203
Make & Model:	MERCEDES-BENZ C200, 1.8 CGI (A)	Chassis No:	WDD2040482A397717
Reg. Date:	02/08/2010 (Man. Year: 2010)	Odometer:	136051 km
Colour:	Grey		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Linglong 6 mm	Rear Left Side:	Linglong 6 mm
Front Right Side:	Linglong 6 mm	Rear Right Side:	Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,570.96	535.50	16,035.46	96.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	720.00	1,550.00	68.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,840.96	1,255.50	17,585.46	93.34
Approved Total (Overridden) (\$\$)		1,000.00		
(\$\$)	18,840.96	1,000.00	17,840.96	94.69
+ GST 7.00/7.00% (\$\$)	1,318.87	70.00	1,248.87	94.69
Nett Amount (\$\$)	20,159.83	1,070.00	19,089.83	94.69

INSPECTION

Date of Assignment:	09/02/2021	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Date Inspected:	08/03/2021 Inspected At:	
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2021)
Parts:	143	MERCEDES-BENZ C200 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY1147D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BUMPER SENSOR	Not Necessary	624.00 FL	*- FL
2	2		*FRONT BUMPER SENSOR HOLDER	Not Necessary	64.00 FL	*- FL
3	1		*FRONT BUMPER	Repair	1,362.00 FL	*- FL
4	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	438.00 FL	*- FL
5	2		*FRONT BUMPER FOGLAMP LED	Not Necessary	1,178.00 FL	*- FL
6	2		*FRONT BUMPER FOGLAMP COVER	Not Necessary	396.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	898.20 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT SPONGE	Not Necessary	312.00 FL	*- FL
9	2		*FRONT BUMPER SIDE GARNISH	Not Necessary	448.00 FL	*- FL
10	1		*FRONT BUMPER CENTRE BRACKET	Not Necessary	358.00 FL	*- FL
11	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	324.00 FL	*- FL
12	1		*FRONT BUMPER UNDER COVER	Not Necessary	462.00 FL	*- FL
13	1		*FRONT BUMPER LOWER SIDE CHROME	Not Necessary	170.00 FL	*- FL
14	1		*FRONT GRILLE	Broken	749.00 FL	*495.00 FL
15	1		*FRONT GRILLE CHROME	Not Necessary	412.00 FL	*- FL
16	1		*TEMPERATURE SENSOR	Not Necessary	425.20 FL	*- FL
17	2		*LED HEADLAMP	Not Necessary	9,196.00 FL	*- FL
18	2		*LED HEADLAMP LOWER BRACKET	Not Necessary	318.00 FL	*- FL
19	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
20	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
21	1		*SET FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
22	1		*FRONT NUMBER PLATE C/W GARNISH	Bent	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,384.40	585.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,813.44	49.50
Total Parts (\$\$)	16,570.96	535.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	280.00
2	PANEL BEATING ON AFFECTED AREAS	New	600.00	400.00
3	TO CHECK ELECTRICAL WIRING	New	120.00	0.00
4	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	150.00	40.00
5	TO REMOVE AND REFIT TURBO COOLER	New	200.00	0.00
6	CHECK AND RESET FAULT CODE LIGHT ON	New	250.00	0.00
7	TO RESPRAY UNDERCOATING	New	150.00	0.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	0.00
Gross Labour Cost (\$)			2,270.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >