

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21001948/KVD3N2**Date:** 26/08/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070170737
Claimant Vehicle No :	SLR3899S	Insured Vehicle No :	SLU3900E
Date of Loss:	01/02/2021	Nature of Claim:	TP
		Claim No:	3101421193SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR3899S	Engine No:	015715
Make & Model:	PORSCHE CAYENNE, 3.0 D (E2-II) TIP E6 (A)	Chassis No:	WP1ZZZ92ZFLA40456
Reg. Date:	07/07/2015 (Man. Year: 2015)	Odometer:	127153 km
Colour:	Metallic Grey		
Engine Capacity:	2967 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/45R20	Rear Tyre Size:	275/45R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,258.70	2,278.71	1,979.99	46.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	680.00	520.00	43.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,458.70	2,958.71	2,499.99	45.80
Approved Total (Overridden) (S\$)		2,350.00		
Nett Amount (S\$)	5,458.70	2,350.00	3,108.70	56.95

INSPECTION

Date of Assignment:	09/02/2021		
Date Inspected:	10/02/2021	Inspected At:	Mega Swift Auto (HQ) 176 Sin Ming Drive, #05-11 Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*AIR GUIDE	Serviceable	276.50 F	*- FL	
2	1		*FOAM PART	Cracked	276.50 F	*276.50 FL	
3	1		*SETTING DEVICE BUMPER COVER	Serviceable	58.50 F	*- FL	
4	1		*BUMPER COVER	Dented/Mtg Cracked	2,255.40 F	*2,255.40 FL	
5	1		*FRONT SPOILER	Serviceable	1,391.80 F	*- FL	
					Sub Total (\$)	4,258.70	2,531.90
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00	253.19
					Total Parts (\$)	4,258.70	2,278.71

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESPRAY FRONT BUMPER	New	650.00	380.00
2	TO DISMANTLE FRONT BUMPER & REINSTALL BACK	New	550.00	300.00
			Gross Labour Cost (S\$)	680.00
			1,200.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >