

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21001949/QGA3Q2  
**Date:** 15/06/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900151729
<b>Claimant Vehicle No :</b>	SJK9352Z	<b>Insured Vehicle No :</b>	SMP1002A
Date of Loss:	05/02/2021	Nature of Claim:	TP
		Claim No:	2098994607SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJK9352Z</b>	Engine No:	4A910105012
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC GLX AT ABS D/AB 2WD 4DR (A)	Chassis No:	JMYSRCY2A8U008423
Reg. Date:	11/11/2008 (Man. Year: 2008)	Odometer:	188333 km
Colour:	White		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,282.10	2,417.30	7,864.80	76.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	470.00	1,310.00	73.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,062.10</b>	<b>2,887.30</b>	<b>9,174.80</b>	<b>76.06</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,300.00</b>		

## Adjuster Report

	(S\$)	12,062.10	2,300.00	9,762.10	80.93
<b>+ GST 7.00/7.00% (S\$)</b>		844.35	161.00	683.35	80.93
<b>Nett Amount (S\$)</b>		<b>12,906.45</b>	<b>2,461.00</b>	<b>10,445.45</b>	<b>80.93</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>			200.00		
<b>+ Doc/Search Fee (S\$)</b>			7.45		
<b>Nett Liability (S\$)</b>			<b>2,668.45</b>		

INSPECTION

Date of Assignment: 09/02/2021

Date Inspected: 22/02/2021

Estimated Period of Repair: 3.0 days

Inspected At:

My Car Consultant Pte Ltd ( Jalan Lam Huat ) (HQ)  
60 Jalan Lam Huat, Carros Centre #05-21  
Singapore 737869

**Adjuster:** OI SUN PIN**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Serviceable	1,445.00 FL	*- FL
2	1		*BONNET LOCK	Serviceable	224.00 FL	*- FL
3	1		*FRONT BUMPER	Deformed	1,145.00 FL	*859.00 FL
4	2		*FRONT BUMPER SIDE RETAINER	Broken	118.00 FL	*118.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Serviceable	452.00 FL	*- FL
6	1		*FRONT BUMPER LOWER GRILLE CENTRE	Serviceable	212.00 FL	*- FL
7	2		*FRONT BUMPER FOGLAMP COVER	Serviceable	159.00 FL	*- FL
8	1		*FRONT BUMPER TOP BEAM	Serviceable	158.00 FL	*- FL
9	1		*FRONT BUMPER TOP BEAM RUBBER	Serviceable	45.00 FL	*- FL
10	1		*FRONT RADIATOR GRILLE	Serviceable	598.00 FL	*- FL
11	1		*FRONT RADIATOR GRILLE LOGO	Serviceable	58.00 FL	*- FL
12	2		*HEADLAMP	Cracked	1,778.00 FL	*1,620.00 FL
13	2		*HEADLAMP LOWER BRACKET	Serviceable	139.00 FL	*- FL
14	2		*FRONT FENDER COWLING	Serviceable	496.00 FL	*- FL
15	1		*FRONT SUPPORT PANEL	Serviceable	612.00 FL	*- FL
16	1		*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	184.00 FL	*- FL
17	1		*AIRCON CONDENSER	Serviceable	1,025.00 FL	*- FL
18	1		*ENGINE UNDERCOVER	Serviceable	321.00 FL	*- FL
19	2		*HORN	Serviceable	300.00 FL	*- FL
20	1		*FRONT NUMBER PLATE	Crumpled	50.00 FS	*50.00 FS
21	1		*FRONT BUMPER LOWER SPOILER	Serviceable	1,500.00 FS	*- FS
22	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*SET FRONT BUMPER LOWER GRILLE CLIPS	Serviceable	50.00 FS	*- FS
24	1		*FRONT BUMPER LOWER COVER CLIPS	Serviceable	50.00 FS	*- FS
25	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Serviceable	30.00 FS	*- FS
26	1		*FRONT FENDER INNER SHIELD CLIP	Serviceable	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,229.00</b>	<b>2,677.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	946.90	259.70
<b>Total Parts (\$\$)</b>	<b>10,282.10</b>	<b>2,417.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
2	REMOVE AND REFIT RADIATOR AND CONDUCT PRESSURE	New	150.00	0.00
3	REFOCUS HEADLAMP BEAM	New	150.00	0.00
4	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	40.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	200.00
6	PANEL BEATING ON AFFECTED AREAS	New	600.00	200.00
			<b>Gross Labour Cost (S\$)</b>	<b>470.00</b>
			<b>1,780.00</b>	<b>470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >