



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1876Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER CENTRE MOULDING	TO REPAIR SEE LABOUR	451.25	-
2	REAR BUMPER BRACKET LH/RH @\$55.80	NOT NECESSARY	111.60	-
	LESS 20% DISCOUNT		-204.45	-
			817.80	-
SPECIAL NETT ITEMS				
1	REAR REVERSE SENSOR (SN)	NOT NECESSARY	180.00	-
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
			230.00	-
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER CENTRE MOULDING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE.		300.00	30.00
			1,000.00	630.00
GRAND TOTAL			2,047.80	630.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				630.00

Report Ref No. NS/INC21001952/T1qf3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.