

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21001958/APA3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100447993
Claimant Vehicle No :	SMR339A	Insured Vehicle No :	GBE5612B
Date of Loss:	07/02/2021	Nature of Claim:	TP
		Claim No:	9672802066SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR339A		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB6744315
Reg. Date:	13/11/2019 (Man. Year: 2018)	Chassis No:	RU31324304
Colour:	Purple	Odometer:	81230 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,349.68	7,945.12	5,404.56	40.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,770.00	2,070.00	2,700.00	56.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,119.68	10,015.12	8,104.56	44.73
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	18,119.68	8,000.00	10,119.68	55.85
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,807.45		
Global Sum Settlement (S\$)		8,800.00		

INSPECTION

Date of Assignment:	09/02/2021	
Date Inspected:	09/02/2021 Inspected At:	Ishare Auto Pte. Ltd. (HQ) 8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER INNER TRIM	O/S Cracked	640.00 FL	*320.00 FL
2	2		*REAR FENDER COWLING	Not Necessary	300.40 FL	*- FL
3	2		*REAR FENDER ARCED GARNISH	Not Necessary	369.40 FL	*- FL
4	1		*REAR BUMPER	Deformed	777.00 FL	*777.00 FL
5	2		*REAR BUMPER REFLECTOR	Not Necessary	302.20 FL	*- FL
6	2		*REAR BUMPER SIDE	Repair	460.00 FL	*- FL
7	2		*REAR BUMPER SIDE RETAINER	Necessary	114.00 FL	*114.00 FL
8	2		*TAIL LAMP	Cracked	950.00 FL	*950.00 FL
9	1		*TAILGATE	Distorted	1,101.00 FL	*1,101.00 FL
10	1		*TAILGATE REVERSE CAMERA	Damaged	816.00 FS	*500.00 FS
11	1		*TAILGATE LOGO	Not Necessary	65.00 FL	*- FL
12	1		*TAILGATE EMBLEM VEZLE	Necessary	69.00 FL	*69.00 FL
13	1		*TAILGATE EMBLEM HYBRID	Necessary	75.00 FL	*75.00 FL
14	1		*TAILGATE OUTER GARNISH	Cracked	396.00 FL	*396.00 FL
15	1		*TAILGATE OUTER MOULDING	Not Necessary	210.00 FL	*- FL
16	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	112.00 FL	*- FL
17	2		*TAILGATE SIDE LAMP	Cracked	728.00 FL	*728.00 FL
18	2		*TAILGATE DAMPER	Not Necessary	302.00 FL	*- FL
19	1		*TAILGATE INNER HOLDER	Not Necessary	52.00 FL	*- FL
20	2		*TAILGATE STOPPER	Not Necessary	38.00 FL	*- FL
21	1		*TAILGATE TOP LOCK	Damaged	145.00 FL	*145.00 FL
22	1		*TAILGATE OUTER SWITCH BUTTOM	Not Necessary	290.00 FL	*- FL
23	1		*TAILGATE LOWER LOCK	Not Necessary	24.70 FL	*- FL
24	1		*TAILGATE INNER TRIM	Cracked	398.60 FL	*398.60 FL
25	1		*TAILGATE LOCK CONNECTOR	Not Necessary	217.00 FL	*- FL
26	1		*TAILGATE WEATHERSTRIP	Cut	168.40 FL	*168.40 FL
27	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	134.00 FL	*134.00 FL
28	1		*BUZZER	Not Necessary	109.00 FL	*- FL
29	1		*REAR END PANEL	Dented	530.00 FL	*530.00 FL
30	1		*REAR END PANEL TOP GARNISH	Cracked	121.00 FL	*121.00 FL
31	1		*REAR FLOOR PANEL BOTTOM GARNISH	Cracked	269.00 FL	*269.00 FL
32	1		*REAR FLOOR PANEL TOP BOARD	Deformed	300.40 FL	*300.40 FL
33	1		*REAR STORAGE BOX	Cracked	495.00 FL	*285.00 FL
34	1		*FRONT DRIVER SEAT	Bent	2,123.20 FS	*1,200.00 FS
35	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
36	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
37	1		*REAR BUMPER TOP PROTECTOR (SPECIAL TYPE)	Missing	650.00 FS	*280.00 FS
38	1		*SET TAILGATE OUTER MOULDING CLIP	Not Necessary	60.00 FS	*- FS
39	1		*SET TAILGATE INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
40	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
41	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS
42	1		*SET TAILLAMP CLIP	Necessary	40.00 FS	*20.00 FS
43	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	60.00 FS	*30.00 FS
44	1		*SET REAR FENDER UPPER TRIM CLIP	Not Necessary	60.00 FS	*- FS
45	1		*SET REAR FENDER COWLING CLIP	Not Necessary	60.00 FS	*- FS
46	1		*SET REAR FENDER ARCED GARNISH CLIP	Not Necessary	60.00 FS	*- FS
47	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
48	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
49	1		*SET REAR FLOOR PANEL BOTTOM GARNISH CLIP	Not Necessary	60.00 FS	*- FS
50	1		*REAR EXHAUST CHROME PIPE (SPECIAL TYPE)	Not Necessary	350.00 FS	*- FS
51	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$)	15,402.30	9,321.40
					- List Item Discount on L Items 20.00/20.00% (\$)	2,052.62	1,376.28
					Total Parts (\$)	13,349.68	7,945.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	250.00	60.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX VIDEO RECORDER	New	80.00	50.00
8	REAR CHASSIS ALIGNMENT	New	250.00	0.00
9	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
11	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPEFICIATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			4,770.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >