

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001959/UBA3Q2
Date: 18/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800083518
Claimant Vehicle No :	FBK8861Y	Insured Vehicle No :	SMC7198Y
Date of Loss:	05/02/2021	Nature of Claim:	TP
		Claim No:	0544205316SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK8861Y	Engine No:	G3E3E0007053
Make & Model:	YAMAHA FZN150, 149cc	Chassis No:	ME1RG1618F2001632
Reg. Date:	11/03/2016 (Man. Year: 2015)	Odometer:	32568 km
Colour:	Red		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70-17	Rear Tyre Size:	140/70-17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Metzeler 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,541.70	526.50	4,015.20	88.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	270.00	690.00	71.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,501.70	796.50	4,705.20	85.52
Approved Total (Overridden) (S\$)		600.00		

Nett Amount (S\$)	5,501.70	600.00	4,901.70	89.09
+ Loss of Use (4.0 x S\$20.00/day) (S\$)		80.00		
Nett Liability (S\$)		680.00		

INSPECTION

Date of Assignment: 08/02/2021

Date Inspected: 16/02/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	70.00 FL	*70.00 FL
2	2		*FORK INNER TUBES	Not Necessary	440.00 FL	*- FL
3	2		*FORK OUTER TUBES	Not Necessary	460.00 FL	*- FL
4	1		*FORK UNDER BRACKET	Not Necessary	245.00 FL	*- FL
5	1		*FRONT RIM	Not Necessary	280.00 FL	*- FL
6	1		*FRONT BRAKE DISC	Not Necessary	155.00 FL	*- FL
7	1		*FRONT RIM SHAFT	Not Necessary	45.00 FL	*- FL
8	1		*FRONT RIM BEARING	Not Necessary	38.00 FL	*- FL
9	2		*FRONT SIGNAL LAMPS	Not Necessary	200.00 FL	*- FL
10	2		*SIDE MIRROR -R/L (Scratched)	Not Consistent With The Impact	120.00 FL	*- FL
11	1		*HANDLE BAR	Not Necessary	135.00 FL	*- FL
12	1		*HANDLE BAR BALANCER (Scratched)	Not Consistent With The Impact	28.00 FL	*- FL
13	1		*SET HAND GRIP	Not Necessary	80.00 FL	*- FL
14	1		*CLUTCH LEVER	Not Necessary	22.00 FL	*- FL
15	2		*FUEL TANK SIDE COVER -R/L	Not Necessary	430.00 FL	*- FL
16	2		*FRONT FOOTREST	Not Necessary	76.00 FL	*- FL
17	2		*FRONT FOOTREST BRACKETS	Not Necessary	180.00 FL	*- FL
18	2		*REAR FOOTREST	Not Necessary	84.00 FL	*- FL
19	2		*REAR SIGNALS	Not Necessary	150.00 FL	*- FL
20	1		*REAR TAIL BOARD	Repair	250.00 FL	*- FL
21	1		*EXHAUST ASSY	Dented	450.00 FL	*450.00 FL
22	1		*EXHAUST PROTECTOR	Distorted	65.00 FL	*65.00 FL
23	1		*SET NUMBER PLATE	Not Necessary	28.00 FS	*- FS
24	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
25	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
26	1		*SET STEERING CONE	Not Necessary	95.00 FS	*- FS
27	1		*E.R.P IU	Not Necessary	200.00 FS	*- FS
28	1		*REAR BOX	Not Necessary	380.00 FS	*- FS
29	1		*REAR BOX BRACKET	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,942.00	585.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	400.30	58.50
Total Parts (\$\$)	4,541.70	526.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	50.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FORCUSING	New	80.00	0.00
3	TO SPRAY PAINTING	New	350.00	120.00
4	TO PROVIDE LABOUR	New	480.00	150.00
			Gross Labour Cost (\$\$)	270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >