

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001963/KPA3Q2**Date:** 15/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100268031
Claimant Vehicle No :	GBF4077Y	Insured Vehicle No :	SKC2063J
Date of Loss:	06/02/2021	Nature of Claim:	TP
		Claim No:	3481055247SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF4077Y		
Make & Model:	FIAT DOBLO, 1.6 D CARGO MJ (M)	Engine No:	263A50007668990
Reg. Date:	14/10/2016 (Man. Year: 2016)	Chassis No:	ZFA26300006D03949
Colour:	Metallic Grey	Odometer:	88581 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,905.00	10,934.50	9,970.50	47.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,480.00	2,130.00	4,350.00	67.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,385.00	13,064.50	14,320.50	52.29
Approved Total (Overridden) (S\$)		10,450.00		
Nett Amount (S\$)	27,385.00	10,450.00	16,935.00	61.84
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	09/02/2021	
Date Inspected:	09/02/2021 Inspected At:	Meng Whee Bros Motor Service (HQ) 10 Ang Mo Kio Industrial Park 2A, #05-25, AMK Autopoint Singapore 568047
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,800.00 F	*1,800.00 FL
2	1		*FRONT BONNET LOCK	Repair	380.00 F	*- FL
3	1		*FRONT SUPPORT PANEL	*Check	780.00 F	*- FL
4	1		*FRONT HEADLAMPS	Cut	1,640.00 F	*1,640.00 FL
5	1		*FRONT GRILLE	Dented	530.00 F	*530.00 FL
6	1		*FRONT GRILLE LOGO	Missing	280.00 F	*280.00 FL
7	1		*FRONT BUMPER	Buckled	760.00 F	*760.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	*Check	400.00 F	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Dented / Distorted	730.00 F	*730.00 FL
10	1		*FRONT BUMPER SIDE RETAINER	N/S Distorted	120.00 F	*60.00 FL
11	1		*FRONT RADIATOR	*Check	900.00 F	*- FL
12	1		*AIR CON CONDENSER	*Check	1,200.00 F	*- FL
13	1		*AUTO FAN ASSY	Serviceable	1,300.00 F	*- FL
14	1		*FRONT FROG LAMP COVER	Serviceable	200.00 F	*- FL
15	1		*REAR DOOR WINDSCREEN MOULDING	Not Necessary	120.00 F	*- FL
16	1		*REAR BOOT DOOR LH	Bent	1,830.00 F	*1,830.00 FL
17	1		*REAR BOOT DOOR TOP HINGE LH	Repair	180.00 F	*- FL
18	1		*REAR BOOT DOOR LOWER HINGE LH	Distorted	175.00 F	*175.00 FL
19	1		*REAR BOOT DOOR BOARD LH	Buckled	320.00 F	*320.00 FL
20	1		*REAR BOOT DOOR LOCK	*Check	480.00 F	*- FL
21	1		*REAR BOOT DOOR MOULDING	Dented	320.00 F	*320.00 FL
22	1		*REAR BOOT DOOR NUMBER PLATE LAMP1	Serviceable	220.00 F	*- FL
23	1		*REAR BOOT DOOR RH	Repair	1,780.00 F	*- FL
24	1		*REAR BOOT WEATHERSTRIPS (50%)	Cut	320.00 FS	*160.00 FS
25	1		*TAIL LAMP LH	Cut	520.00 F	*520.00 FL
26	1		*REAR BUMPER	Bent	1,380.00 F	*1,380.00 FL
27	1		*REAR BUMPER TOP GARNISH COVER	Buckled	420.00 F	*420.00 FL
28	1		*REAR BUMPER SIDE RETAINER	Distorted	100.00 F	*100.00 FL
29	1		*REAR BUMPER REFLECTOR	Cracked	180.00 F	*180.00 FL
30	1		*REAR BUMPER REVERSE SENSOR ORI	Scratched	400.00 FS	*200.00 FS
31	1		*REAR BUMPER REINFORCEMENT	*Check	420.00 F	*- FL
32	1		*REAR EMBLEM	Necessary	100.00 F	*100.00 FL
33	1		*REAR EMBLEM LOGO	Necessary	120.00 F	*120.00 FL
34	1		*REAR EMBLEM PROFFESIONAL	Necessary	100.00 F	*100.00 FL
35	1		*REAR EMBLEM DOBLO	Necessary	100.00 F	*100.00 FL
36	1		*REAR EMBLEM MAX	Necessary	80.00 F	*80.00 FL
37	1		*REAR EMBLEM 90	Necessary	60.00 F	*60.00 FL
38	1		*REAR EMBLEM MULTIJET2	Necessary	100.00 F	*100.00 FL
39	1		*SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	20,905.00	12,105.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	1,170.50
Total Parts (S\$)	20,905.00	10,934.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL REAR DOOR GLASS	New	280.00	80.00
2	TO REMOVE AND INSTALL ,WELD AND CUT REAR END PANEL REAR BUMPER ,TAIL LAMP ,ETC AND STRAIGHTEN REAR CHASSIS FRAME	New	900.00	550.00
3	TO REMOVE AND INSTALL FRONT SUPPORT PANEL ,HEADLAMP,RADIATOR BUMPER ,ETC AND STRAIGHTEN FRONT CHASSIS FRAME (*Check)	New	1,200.00	0.00
4	TO CHECK FRONT AND REAR WIRING SYSTEM	New	200.00	40.00
5	TO RESPRAY ANTI RUST ON AFFECTED AREA	New	300.00	60.00
6	TO APPLY PUTTY ,PRIMER AND RESPRAY PAINT ON DAMAGED SECTION	New	2,800.00	1,400.00
7	TO VACUUM AND TOP UP (*Check)	New	800.00	0.00
Gross Labour Cost (S\$)			6,480.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >