

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21001964/UGS3Q2**Date:** 01/12/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
Claimant Vehicle No :	YN7930A	Insured Vehicle No :	SHD2152R
Date of Loss:	22/12/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002795

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN7930A	Engine No:	6M60198244
Make & Model:	MITSUBISHI FUSO, 3.0 D FM65FM2RDEB (M)	Chassis No:	FM65FMA20009
Reg. Date:	02/04/2015 (Man. Year: 2014)	Odometer:	248495 km
Colour:	White		
Engine Capacity:	7545 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,430.00	2,570.00	5,860.00	69.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	700.00	730.00	51.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,860.00	3,270.00	6,590.00	66.84
Approved Total (Overridden) (S\$)		2,600.00		

Nett Amount (S\$)	9,860.00	2,600.00	7,260.00	73.63
+ Loss of Use (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,967.45		

INSPECTION

Date of Assignment: 09/02/2021

Date Inspected: 09/02/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)
Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 May 2021)	
Parts:	N/A	MITSUBISHI FUSO 3.0 D FM65FM2RDEB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN7930A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL LAMP RH	Cracked	280.00 FS	*210.00 FS
2	1		*REAR SAFETY BAR CENTRE ASSY	Bent	1,800.00 FS	*1,200.00 FS
3	1		*REAR SAFETY BAR RH	Distorted	1,050.00 FS	*600.00 FS
4	1		*REAR HYDRAULIC PUMP INNER	Serviceable	4,500.00 FS	*- FS
5	1		*REAR HYDRAULIC PUMP DUST COVER INNER RH	Torn	420.00 FS	*280.00 FS
6	1		*REAR HYDRAULIC PUMP DUST COVER OUTER RH	Twisted	380.00 FS	*280.00 FS
Total Parts (S\$)					8,430.00	2,570.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	TO DISMANTLE & REPLACE HYDRAULIC PUMP DUST COVER}	New	200.00	80.00
3	TO TEST & REALIGNMENT HYDRAULIC PUMP }	New	380.00	0.00
4	LABOR FOR PANEL BEATING , CUT , WELD , STRAIGHTEN & REPLACING PARTS ETCS	New	500.00	400.00
5	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	300.00	200.00
			Gross Labour Cost (S\$)	700.00
			1,430.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >