

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21001965/UGS3Q2
Date: 18/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SKV6654C	Insured Vehicle No :	SMQ2435Y
Date of Loss:	04/02/2021	Nature of Claim:	TP
		Claim No:	7191202815SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV6654C	Engine No:	1AZE099519
Make & Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Chassis No:	MR053BK4107028946
Reg. Date:	22/05/2008 (Man. Year: 2008)	Odometer:	316539 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,033.60	4,543.82	14,489.78	76.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	1,740.00	1,900.00	52.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,673.60	6,283.82	16,389.78	72.29
Approved Total (Overridden) (S\$)		5,000.00		

(S\$)	22,673.60	5,000.00	17,673.60	77.95
+ GST 7.00/7.00% (S\$)	1,587.15	350.00	1,237.15	77.95
Nett Amount (S\$)	24,260.75	5,350.00	18,910.75	77.95
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,837.45		

INSPECTION

Date of Assignment: 09/02/2021

Date Inspected: 09/02/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented / Buckled	1,488.20 F	*1,465.10 FL
2	1		*BONNET LOCK	Serviceable	166.20 F	*- FL
3	2		*BONNET HINGES	Not Necessary	190.00 F	*- FL
4	1		*BONNET RUBBER	Necessary	62.00 F	*62.00 FL
5	1		*BONNET INSULATOR	Not Necessary	282.00 F	*- FL
6	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
7	1		*FRONT BUMPER	Distorted	1,088.20 F	*552.10 FL
8	1		*FRONT BUMPER TOW COVER	Not Necessary	35.00 F	*- FL
9	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	148.50 F	*- FL
10	1		*FRONT FOG LAMPS	N/S Cracked	900.00 F	*399.50 FL
11	1		*FRONT FOG LAMP GRILLS	M/S Twisted	206.00 F	*103.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	482.30 F	*482.30 FL
13	1		*FRONT BUMPER TOP RUBBER	Necessary	112.00 F	*112.00 FL
14	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
15	2		*FRONT BUMPER RETAINERS	Not Necessary	130.00 F	*- FL
16	1		*FRONT BUMPER LOGO	Necessary	64.50 F	*64.50 FL
17	1		*FRONT GRILLE	Cracked	381.10 F	*381.10 FL
18	1		*FRONT FOG LAMP MOULDING	N/S Cracked	188.50 F	*122.30 FL
19	1		*HEADLAMP	N/S Cracked	5,700.00 F	*1,880.20 FL
20	1		*FRONT SUPPORT PANEL	Repair	1,225.10 F	*- FL
21	1		*FRONT AIR DUCT	Not Necessary	299.20 F	*- FL
22	1		*AIR CON CONDENSER	Not Necessary	1,298.10 F	*- FL
23	1		*AIR CON CONDENSER SIDE GARNISH O/S	Not Necessary	125.10 F	*- FL
24	1		*RADIATOR	Not Necessary	1,688.10 F	*- FL
25	1		*RADIATOR FAN COWLING	Not Necessary	411.20 F	*- FL
26	1		*WIPER TANK	Not Necessary	311.20 F	*- FL
27	1		*WIPER TANK MOTOR	Not Necessary	185.00 F	*- FL
28	1		*HORN UNIT	Not Necessary	105.00 F	*- FL
29	1		*FRONT FENDER N/S	Repair	899.10 F	*- FL
30	1		*FRONT FENDER INNER SHIELDS	N/S Torn	562.00 F	*281.00 FL
31	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 F	*50.00 FL
32	1		*FRONT LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
33	1		*BOL RADIATOR COOLANT	Not Necessary	50.00 FS	*- FS
34	1		*BOL AIR CON OIL	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Sub Total (\$)	19,033.60
					- List Item Discount on L Items 0.00/25.00% (\$)	0.00
					Total Parts (\$)	19,033.60
						6,045.10
						1,501.28
						4,543.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
3	TO REFILL AIR CON GAS	New	120.00	100.00
4	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	500.00	0.00
5	TO SPRAY RUST PROOFING	New	120.00	30.00
6	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,200.00	600.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	980.00
Gross Labour Cost (S\$)			3,640.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >