



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 76H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	HEADLAMP LH (WCP)	SERVICEABLE	4,200.00	-
1	HEADLAMP RH (WCP)	SERVICEABLE	3,000.00	-
1	HEADLAMP PANEL LH (WCP)	TO REPAIR SEE LABOUR	220.00	-
1	HEADLAMP PANEL RH (WCP)	TO REPAIR SEE LABOUR	130.00	-
2	FRONT GRILLE LH & RH (WCP)	CRACKED	170.00	170.00
1	FRONT BUMPER (WCP)	BUCKLED / CRACKED	850.00	820.00
2	FRONT BUMPER SIDE RETAINER LH & RH (WCP)	SERVICEABLE	48.00	-
15	FRONT BUMPER RIVET (WCP)	NECESSARY	22.50	22.50
1	FRONT BUMPER LOWER AIR GRILLE (WCP)	SERVICEABLE	55.00	-
1	FRONT BUMPER REINFORCEMENT (WCP)	BENT	400.00	400.00
2	FRONT BUMPER REINFORCEMENT BRACKET LH & RH (WCP)	TO REPAIR SEE LABOUR	110.00	-
1	FRONT BUMPER SPONGE (WCP)	CRACKED	40.00	40.00
1	FRONT BUMPER EMBLEM (WCP)	NOT NECESSARY	60.00	-
2	FRONT BUMPER PARKING SENSOR INNER (WCP)	MISSING	260.00	260.00
1	SET FRONT BUMPER PARKING SENSOR HOLDER (WCP)	NOT NECESSARY	50.00	-
1	FRONT BUMPER PARKING SENSOR WIRE HARNESS (WCP)	CUT	120.00	120.00
1	RADIATOR AIR GUIDE (WCP)	CRACKED	300.00	240.00
2	FRONT BRACE PANEL LH & RH (WCP)	DISTORTED	30.00	30.00
1	RADIATOR TOP PANEL FRT (WCP)	BENT	135.00	135.00
1	AIR CON CONDENSER (WCP)	PUNCTURE	680.00	680.00
1	RADIATOR ASSY (WCP)	SERVICEABLE	650.00	-
1	INTERCOOLER (WCP)	SERVICEABLE	420.00	-
2	FOGLAMP COVER LH & RH (WCP)	SERVICEABLE	160.00	-
2	FOGLAMP COVER MOULDING LH & RH (NPA)(WCP)	SERVICEABLE	-	-
	COST PLUS 10%		1,211.05	291.75
			13,321.55	3,209.25

Report Ref No. CS/SMO21001969/Kqf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	NUMBER PLATE (SN)	DENTED	35.00	35.00
1	RADIATOR COOLANT (SN)	NOT NECESSARY	30.00	-
			65.00	35.00
	<b><u>LABOUR</u></b>			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES.RADIATOR AND HOSES,VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		100.00	100.00
	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT.		180.00	120.00
	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL LH,HEADLAMP PANEL RH AND FRONT BUMPER REINFORCEMENT BRACKET LH & RH.		600.00	400.00
	TO SPRAY FRONT BUMPER SUPPORT PANEL.		400.00	250.00
			1,320.00	890.00
<b>GRAND TOTAL</b>			<b>14,706.55</b>	<b>4,134.25</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,134.25</b>

Report Ref No. CS/SMO21001969/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.