

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21001973/DBS3Q2
Date: 23/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100465979
Claimant Vehicle No :	SJH707J	Insured Vehicle No :	SLC5302M
Date of Loss:	08/02/2021	Nature of Claim:	TP
		Claim No:	8247344002SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH707J	Engine No:	L13A4084773
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GE61075387
Reg. Date:	25/07/2008 (Man. Year: 2008)	Odometer:	232142 km
Colour:	Blue		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,228.64	4,862.16	10,366.48	68.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,150.00	2,470.00	3,680.00	59.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,378.64	7,332.16	14,046.48	65.70
Approved Total (Overridden) (S\$)		5,850.00		

(S\$)	21,378.64	5,850.00	15,528.64	72.64
+ GST 7.00/7.00% (S\$)	1,496.50	409.50	1,087.00	72.64
Nett Amount (S\$)	22,875.14	6,259.50	16,615.64	72.64
+ Loss of Use (14.0 x S\$60.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		65.45		
Nett Liability (S\$)		7,164.95		
Global Sum Settlement (S\$)		7,150.00		

INSPECTION

Date of Assignment: 09/02/2021

Date Inspected: 10/02/2021

Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
 Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,314.00 FL	*771.50 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	295.60 FL	*195.60 FL
3	1		*TAILGATE WIPER MOTOR	Not Necessary	525.00 FL	*- FL
4	1		*TAILGATE WIPER BLADE	Not Necessary	98.60 FL	*- FL
5	1		*TAILGATE CENTER GARNISH	Not Necessary	369.80 FL	*- FL
6	1		*TAILGATE HONDA LOGO	Necessary	55.70 FL	*55.70 FL
7	1		*TAILGATE FIT EMBLEM	Necessary	75.00 FL	*75.00 FL
8	2		*TAILGATE NO.PLATE LAMP LH/RH	Not Necessary	197.00 FL	*- FL
9	1		*TAILGATE SWITCH	Not Necessary	275.50 FL	*- FL
10	1		*TAILGATE LOCK	Damaged	257.10 FL	*189.90 FL
11	1		*TAILGATE STRIKER LOCK	Bent	97.50 FL	*48.90 FL
12	1		*TAILGATE INNER TRIM BOARD	Mtg Cracked	596.80 FL	*192.30 FL
13	1		*TAILGATE WEATHER STRIP	Deformed	292.30 FL	*165.60 FL
14	1		*SET TAILGATE STOPPERS	Serviceable	60.00 FL	*- FL
15	2		*TAILGATE DAMPER LH/RH	Not Necessary	584.20 FL	*- FL
16	2		*TAILGATE HINGE LH/RH	Not Necessary	196.00 FL	*- FL
17	2		*TAIL LAMP LH/RH	Mtg Cracked / Broken	1,089.20 FL	*793.60 FL
18	2		*TAIL LAMP PANEL LH/RH	Dented	750.60 FL	*356.60 FL
19	1		*REAR BUMPER	Dented	893.70 FL	*497.20 FL
20	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	137.80 FL	*- FL
21	2		*REAR BUMPER BRACKET LH/RH	Not Necessary	396.00 FL	*- FL
22	1		*REAR KEYLESS BUZZER	Not fitted	285.00 FL	*- FL
23	1		*REAR END PANEL	Dented	1,020.00 FL	*365.30 FL
24	1		*REAR END PANEL TOP GARNISH	Deformed / Bent	260.80 FL	*140.20 FL
25	1		*SPARE WHEEL PANEL	Dented	1,397.00 FL	*637.40 FL
26	1		*SPARE WHEEL PANEL TOP BOARD	Serviceable	394.70 FL	*- FL
27	1		*SPARE WHEEL QUARTER PANEL LH/RH	O/S Dented / N/S Not Necessary	625.60 FL	*312.80 FL
28	1		*SPARE WHEEL STYROFOAM TOOL BOX	Broken	320.00 FL	*220.00 FL
29	1		*REAR EXHAUST PIPE	Repair	855.80 FL	*- FL
30	1		*REAR EXHAUST MOUNTING	Not Necessary	56.80 FL	*- FL
31	1		*REAR EXHAUST HEAT SHIELD	Serviceable	83.50 FL	*- FL
32	1		*REAR FENDER LH/RH	O/S Repair / N/S Not Necessary	2,118.60 FL	*- FL
33	2		*REAR FENDER INNER SHIELD LH/RH	Not Necessary	187.40 FL	*- FL
34	2		*REAR FENDER INNER TRIM BOARD LH /RH	Broken	1,331.20 FL	*572.60 FL
35	2		*REAR FENDER AIR DUCT LH/RH	Not Necessary	192.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
37	1		*TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
38	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
39	1		*TAILGATE CENTER GARNISH GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*20.00 FS
41	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
42	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
43	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
44	1		*SPARE WHEEL PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
45	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
47	1		*REAR NO.PLATE & CASING	Serviceable	100.00 FS	*- FS
48	1		*SET REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,765.80	5,980.20
- List Item Discount on L Items 20.00/20.00% (\$)	3,537.16	1,118.04
Total Parts (\$)	15,228.64	4,862.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	500.00	120.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	1,000.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	1,000.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	150.00	60.00
6	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
7	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	100.00	40.00
8	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	300.00	120.00
9	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
10	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			6,150.00	2,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >