

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21001979/AQD3Q2
Date: 19/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100501064
Claimant Vehicle No :	SLU4055M	Insured Vehicle No :	EJ8180Z
Date of Loss:	08/02/2021	Nature of Claim:	TP
		Claim No:	3694727196SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU4055M	Engine No:	PE21019914
Make & Model:	MAZDA 3, 2.0 (A)	Chassis No:	JM6BN2478J0193616
Reg. Date:	30/11/2017 (Man. Year: 2017)	Odometer:	33095 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,443.92	3,294.88	9,149.04	73.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	1,560.00	2,290.00	59.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,293.92	4,854.88	11,439.04	70.20
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	16,293.92	3,800.00	12,493.92	76.68

INSPECTION

Date of Assignment:	09/02/2021		
Date Inspected:	17/02/2021	Inspected At:	Ysk Auto Workshop (HQ) No.1 Kaki Bukit Avenue 6, #01-49 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-LH	Repair	581.60 FL	*- FL
2	1		*FRONT FENDER INNER SHIELD	Not Necessary	162.40 FL	*- FL
3	15		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	82.50 FL	*- FL
4	1		*FRONT DOOR-LH	Dented	1,589.60 FL	*1,062.00 FL
5	1		*FRONT DOOR OUTER HANDLE	Not Necessary	191.60 FL	*- FL
6	1		*FRONT DOOR SIDE MIRROR	Damaged	821.60 FL	*821.60 FL
7	1		*FRONT DOOR SIDE MIRROR COVER	Repair	180.90 FL	*- FL
8	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	141.20 FL	*- FL
9	1		*FRONT DOOR GLASS RUN CHANNEL	Not Necessary	193.60 FL	*- FL
10	1		*FRONT DOOR GLASS REGULATOR	Not Necessary	481.90 FL	*- FL
11	1		*FRONT DOOR INNER LOCK	Not Necessary	431.60 FL	*- FL
12	1		*FRONT DOOR W/STRIP	Not Necessary	181.70 FL	*- FL
13	1		*FRONT DOOR CHECKER	Not Necessary	89.90 FL	*- FL
14	1		*FRONT SHOCK ABSORBER-LH	Not Necessary	491.20 FL	*- FL
15	1		*FRONT LOWER ARM	Not Necessary	591.60 FL	*- FL
16	1		*FRONT KNUCKLE ARM	Not Necessary	580.50 FL	*- FL
17	1		*FRONT WHEEL HUB	Not Necessary	280.90 FL	*- FL
18	1		*FRONT WHEEL BEARING	Not Necessary	211.30 FL	*- FL
19	1		*REAR DOOR-LH	Dented	1,682.60 FL	*1,085.00 FL
20	1		*REAR DOOR OUTER HANDLE	Not Necessary	196.60 FL	*- FL
21	1		*REAR DOOR GLASS OUTER MOULDING	Not Necessary	141.20 FL	*- FL
22	1		*REAR DOOR GLASS RUN CHANNEL	Not Necessary	191.60 FL	*- FL
23	1		*REAR DOOR GLASS REGULATOR	Not Necessary	461.30 FL	*- FL
24	1		*REAR DOOR 1/4 GLASS RUBBER	Not Necessary	86.90 FL	*- FL
25	1		*REAR DOOR W/STRIP	Not Necessary	181.30 FL	*- FL
26	1		*REAR DOOR CHECKER	Not Necessary	89.90 FL	*- FL
27	1		*REAR SHOCK ABSORBER-LH	Not Necessary	421.60 FL	*- FL
28	1		*REAR TRAILING ARM	Not Necessary	581.90 FL	*- FL
29	1		*REAR TOP ARM	Not Necessary	280.60 FL	*- FL
30	1		*REAR LOWER ARM	Not Necessary	311.30 FL	*- FL
31	1		*REAR KNUCKLE ARM	Not Necessary	560.90 FL	*- FL
32	1		*REAR WHEEL HUB BEARING	Not Necessary	531.60 FL	*- FL
33	1		*REAR SPORT WHEEL-LH	Cut	550.00 FS	*400.00 FS
34	1		*REAR TYRE	Not Necessary	350.00 FS	*- FS
35	1		*SET REAR DOOR BLACK TAPE	Necessary	120.00 FS	*60.00 FS
36	1		*SET FRONT DOOR BLACK TAPE	Necessary	120.00 FS	*60.00 FS
37	1		*FRONT SPORT WHEEL-LH	Cut	550.00 FS	*400.00 FS
38	1		*FRONT TYRE	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,044.90	3,888.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,600.98	593.72
Total Parts (\$\$)	12,443.92	3,294.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT & REAR ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE,REFIX FRONT & REAR UNDERCARRIAGE	New	600.00	0.00
3	TO RESPRAY UNDERCOATING	New	150.00	50.00
4	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
5	TO RESPRAY PAINTING AND ETC	New	1,400.00	800.00
6	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS	New	1,500.00	600.00
Gross Labour Cost (\$\$)			3,850.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >