

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21001984/T1TF3E2

Date: 19/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100401592
Claimant Vehicle No :	PC5394A	Insured Vehicle No :	SKR3742Y
Date of Loss:	08/02/2021	Nature of Claim:	TP
		Claim No:	6067620485SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC5394A		
Make & Model:	MERCEDES-BENZ VIANO, 2.2 D CDI (W639) (A)	Engine No:	65194031142978
Reg. Date:	12/09/2012 (Man. Year: 2012)	Chassis No:	WDF63981523747494
Colour:	Black	Odometer:	185502 km
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R16	Rear Tyre Size:	225/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	10/02/2021	
Date Inspected:	16/02/2021 Inspected At:	Carsmith Private Limited (HQ) 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE Singapore 417807
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER CENTRE	Deformed	0.00 F	*- F
2	1		*REAR BUMPER SIDE LH	Deformed	0.00 F	*- F
3	1		*REAR BUMPER LH SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR BUMPER CENTRE BRACKET	Cracked	0.00 F	*- F
5	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
6	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
7	1		*REAR LH TAILLAMP LOWER GARNISH	Deformed	0.00 F	*- F
8	1		*LH REFLECTOR	Cut	0.00 F	*- F
9	1		*TAILGATE	Bent	0.00 F	*- F
10	1		*TAILGATE EMBLEM VIANO	Necessary	0.00 F	*- F
11	1		*TAILGATE EMBLEM MB LOGO	Necessary	0.00 F	*- F
12	1		*TAILGATE EMBLEM CDI 2.2	Necessary	0.00 F	*- F
13	1		*70KM/H STICKER	Necessary	0.00 F	*- F
14	1		*REAR END PANEL	Repair	0.00 F	*- F
15	1		*LH TAILLAMP	* Check	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >