



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 7811T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	WING MIRROR MOUNTING RH (SN)	CUT	516.00	515.50
1	WING MIRROR CAP RH (SN)	MISSING	191.00	191.00
1	WING MIRROR GLASS RH (SN)	MISSING	309.00	308.50
1	CORNER TRIM RH (SN)	CUT	46.00	45.30
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
1	FRONT DOOR WINDOW - RH (SN) (ADDITIONAL)	CUT	197.00	196.50
			1,359.00	1,256.80
<u>LABOUR</u>				
	TO DISMANTLE RHS DOOR PANEL TRIM.		400.00	400.00
	TO RESPRAY RHS WING MIRROR COVER AND RHS FRONT DOOR.		1,900.00	200.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			2,492.00	792.00
GRAND TOTAL			3,851.00	2,048.80
RECOMMENDED COST OF REPAIRS				2,048.80

Report Ref No. CS/UOI21001988/Avd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.