

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722
 Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SLS4394U
 Vehicle Model : Toyota Vellfire

Date : 23.07.2021

NOT Notified
895h
Return After Paint 2 days

No.	Qty	Estimate Repair Cost	Parts List Items	Price	Status
1	1	Rear bumper		\$ 1,449.95	X
2	2	Rear bumper brackets		\$ 124.20	X
3	2	Rear bumper retainers		\$ 220.70	X
4	1	Rear bumper reflector RH		\$ 98.40	X
5	1	Rear bumper reverse sensor wiring		\$ 455.90	X
6	1 set	Rear bumper clips		\$ 40.00	X
7	1	Side bumper RH		\$ 201.35	X
10	1	Side bumper retainer RH		\$ 116.10	X
Total				\$ 2,706.60	

<u>Labour</u>		Price	Status
1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 800.00	180/
2	To putty and respray painting on affected areas.	\$ 600.00	300/
3	To remove, replace rear tailgate fittings to facilitate repair.	\$ 300.00	X
4	To remove, replace reverse sensor.	\$ 150.00	X
5	To check wiring and lightings.	\$ 80.00	15/
Total Labour		\$ 1,930.00	
Total Parts and Labour		\$ 4,636.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____